

WO Number	WO Complaint	WO Correction	Unit ID	@	Meter Amt	Meter Type	Order Date	Deadline Date	Start Date	Complete Date	Assigned To
306894	TRACK CAME OFF	REINSTALLED TRACK	01030008	F	9625	HR	18/06/2020	18/06/2020	18/06/2020	18/06/2020	MCGLOSSON, PAUL C.
298376	LOWER WINDOW BROKEN	REPLACED WINDOW	01030008	P	9471	HR	13/01/2020	23/01/2020	23/01/2020	23/01/2020	GASCON, RONALD J.
290752	CAB STRUCTURE IS BREAKING AT THE GRAB RAIL	ADMINISTRATIVELY CLOSED	01030008	F	0	HR	22/08/2019	25/09/2019	11/09/2019	25/09/2019	COLUMBUS EQUIP CO. (PARTS & SERVICE)
282892	TWO TRACK PADS ARE MISSING AND OTHERS ARE LOOSE OR MISSING BOLTS	CHECKED AND REPLACED NEEDED BOLTS	01030008	P	0	HR	11/04/2019	12/04/2019	12/04/2019	12/04/2019	HOLLINGSWORTH, AUSTIN
282891	WORK LIGHT ON TOP OF CAB IS BROKEN	REPLACED WORK LIGHT	01030008	P	0	HR	11/04/2019	12/04/2019	12/04/2019	12/04/2019	HOLLINGSWORTH, AUSTIN
282890	REPLACE TWO BROKEN MIRROR, LEFT FRONT OF CAB AND NEAR EXHAUST	REPLACED MIRRORS	01030008	P	0	HR	11/04/2019	12/04/2019	12/04/2019	12/04/2019	HOLLINGSWORTH, AUSTIN
280738	BARELY CRANKS, WONT START	REPLACED BATTERIES	01030008	F	8890	HR	01/03/2019	04/03/2019	01/03/2019	04/03/2019	BERGER, JOSEPH DALE
273914	FILL AUTO GREASER	FILLED AUTO GREASER	01030008	F	8561	HR	17/10/2018	17/10/2018	17/10/2018	17/10/2018	WILLIS, AARON
273910	HYDRAULIC LEAK @ HOSE FROM STICK TO BREAKER	REPLACED O-RING	01030008	F	8561	HR	17/10/2018	17/10/2018	17/10/2018	17/10/2018	WILLIS, AARON
273787	FRONT WINDSHIELD BROKEN	REPLACED ROLLERS	01030008	F	8593	HR	16/10/2018	29/10/2018	19/10/2018	29/10/2018	DISNEY, WALTER RYAN
273290	CAB DOOR WONT STAY SHUT	REPLACED ROLLER ON DOOR	01030008	F	8547	HR	09/10/2018	10/10/2018	10/10/2018	10/10/2018	BURGESS, MICHAEL
273271	TRACKS ARE LOOSE	TIGHTEN TRACKS TO SPEC	01030008	F	8538	HR	08/10/2018	08/10/2018	08/10/2018	08/10/2018	MCGLOSSON, PAUL C.
273270	HAMMER NOT HITTING HARD ENOUGH	OPENED VALVE AND GREASED	01030008	F	8538	HR	08/10/2018	08/10/2018	08/10/2018	08/10/2018	MCGLOSSON, PAUL C.
269550	BOOM LIFT CYLINDERS ROD END HAVE .148 AT PIN	SOLD	01030008	F	0	HR	08/08/2018	08/08/2018	08/08/2018	08/08/2018	MCGLOSSON, PAUL C.
269530	RIGHT WORK LIGHT INOP	INSTALLED NEW BULB	01030008	F	8367	HR	07/08/2018	07/08/2018	07/08/2018	07/08/2018	CRAMER, NICHOLAS
269475	AUX HYDRAULIC STEEL LINES ON BOOM ARE BENT / DAMAGED	SOLD	01030008	F	0	HR	06/08/2018	06/08/2018	06/08/2018	06/08/2018	CRAMER, NICHOLAS
269380	RIGHT FRONT TRACK STEP BENT / PULLED FRAME OUTWARD	REBENT TRACK FRAME, REWELDED STEP	01030008	F	8372	HR	04/08/2018	07/08/2018	07/08/2018	07/08/2018	MCGLOSSON, PAUL C.
269378	REPLACE BAD TRACK ROLLERS	REPLACED NEEDED TRACK ROLLERS	01030008	F	8372	HR	04/08/2018	07/08/2018	07/08/2018	07/08/2018	MCGLOSSON, PAUL C.
269372	TRACKS ARE TOO TIGHT	ADJUSTED TRACKS TO .850 SAG	01030008	F	8367	HR	04/08/2018	03/08/2018	03/08/2018	03/08/2018	MCGLOSSON, PAUL C.
269365	SAFETY CABIN WINDOW HAMMER MISSING	INSTALLED HAMMER	01030008	F	8372	HR	03/08/2018	16/08/2018	16/08/2018	16/08/2018	MCGLOSSON, PAUL C.
269364	STEAM OFF MACHINE / ENGINE COMPARTMENT, HYDRAULIC PUMP COMPARTMENT	WASHED AND STEAMED	01030008	F	8367	HR	03/08/2018	06/08/2018	06/08/2018	06/08/2018	DEUFEMIA JR., VINCENTO
269363	REPLACE CABIN A/C FILTER	REPLACED	01030008	F	8367	HR	03/08/2018	06/08/2018	06/08/2018	06/08/2018	MCGLOSSON, PAUL C.
269360	HYDRAULIC TANK SIGHT GLASS BROKEN	INSTALLED NEW SIGHT GLASS & FITTINGS	01030008	F	8367	HR	07/08/2018	07/08/2018	07/08/2018	07/08/2018	CRAMER, NICHOLAS
269284	UPDATE FIRE EXTINGUISHER	INSTALLED NEW FIRE EXTINGUISHER	01030008	F	8367	HR	03/08/2018	02/08/2018	02/08/2018	02/08/2018	CRAMER, NICHOLAS
269283	REPLACE ENGINE AND A/C BELT	INSTALLED NEW BELTS	01030008	F	8367	HR	03/08/2018	06/08/2018	06/08/2018	06/08/2018	CRAMER, NICHOLAS
269269	REPAIR MUFFLER HEAT COVER	SECURED HEAT COVER AROUND MUFFLER	01030008	F	8367	HR	02/08/2018	02/08/2018	02/08/2018	02/08/2018	CRAMER, NICHOLAS
269268	HOSE FOR HYDRAULIC TANK VENT MISSING	INSTALLED NEW HOSE	01030008	F	8367	HR	02/08/2018	06/08/2018	06/08/2018	06/08/2018	CRAMER, NICHOLAS
269267	WINDSHIELD WASHER RESEVIOIR SUPPLY LINE BROKE	REPLACED DAMAGED SECTION OF LINE	01030008	F	8367	HR	02/08/2018	06/08/2018	06/08/2018	06/08/2018	MCGLOSSON, PAUL C.
269266	BELLY PANEL DAMAGED UNDERNEATH FUEL TANK	INSTALLED NEW BELLY PANEL	01030008	F	8367	HR	02/08/2018	06/08/2018	06/08/2018	06/08/2018	CRAMER, NICHOLAS
269118	REMOTE ENGINE OIL FILTER LINES LEAKING	INSTALLED NEW HOSES	01030008	F	8367	HR	01/08/2018	06/08/2018	06/08/2018	06/08/2018	CRAMER, NICHOLAS
269093	BUCKET CYLINDER ROD END STEEL LINE HAS BENT MOUNTING BOLT	REPLACED TUBE AND MOUNTING	01030008	F	8372	HR	31/07/2018	16/08/2018	16/08/2018	16/08/2018	MCGLOSSON, PAUL C.
269092	FUEL WATER SEPARATOR WIRING DAMAGED AT SENSOR PIGTAIL	REPLACED PIGTAIL, CUT OUT DAMAGED WIRING	01030008	F	8367	HR	31/07/2018	03/08/2018	03/08/2018	03/08/2018	MCGLOSSON, PAUL C.
269091	REPLACE ZERO UNIT # IN FRONT OF CAB	REPLACED	01030008	F	8367	HR	31/07/2018	03/08/2018	03/08/2018	03/08/2018	MCGLOSSON, PAUL C.
269089	STEPS ARE BENT / DAMAGED FOR ENGINE ACCESS	REBUILT STEPS	01030008	F	8365	HR	31/07/2018	02/08/2018	02/08/2018	02/08/2018	WESLEY, JAMES M.
269088	LEFT TRACK STEPS NEED EXTENSIONS	INSTALLED NEW EXTENSIONS	01030008	F	8372	HR	31/07/2018	06/08/2018	06/08/2018	06/08/2018	CRAMER, NICHOLAS
269087	HYDRAULIC LEAK AT LINE IN MAIN VALVE STACK COMPARTMENT	REPLACED HOSE	01030008	F	8367	HR	31/07/2018	03/08/2018	03/08/2018	03/08/2018	MCGLOSSON, PAUL C.
269085	DOOR HANDLE MOUNTING BOLT MISSING	REPLACED MISSING BOLTS	01030008	F	8372	HR	31/07/2018	31/07/2018	31/07/2018	31/07/2018	CRAMER, NICHOLAS
269084	PM2 INSPECTION	PERFORMED INSPECTION	01030008	F	8372	HR	31/07/2018	31/07/2018	07/08/2018	07/08/2018	MCGLOSSON, PAUL C.
268852	CONTROL PANEL BROKE OFF	REPLACED CONTROL PANEL	01030008	F	8367	HR	27/07/2018	06/08/2018	06/08/2018	06/08/2018	MCGLOSSON, PAUL C.
268755	FILL AUTO GREASER	FILLED GREASER	01030008	F	8356	HR	25/07/2018	26/07/2018	26/07/2018	26/07/2018	WILLIS, AARON
268686	A BRACKET FOR A STEEL LINE ON TOP OF BOOM IS MISSING OR BROKEN	INSTALLED NEW CLAMP	01030008	F	8341	HR	24/07/2018	24/07/2018	24/07/2018	24/07/2018	OEDER, KYLE D.
268291	WASH AND STEAM	WASHED AND STEAMED	01030008	F	8324	HR	17/07/2018	17/07/2018	17/07/2018	17/07/2018	WHITE, WILLIAM
268214	ADD SKIRTING AROUND HAMMER	ADDED SKIRTING TO THE BOTTOM OF HAMMER	01030008	F	0	HR	16/07/2018	17/07/2018	17/07/2018	17/07/2018	BERGER, JOSEPH DALE
267934	MIRROR ABOVE ENGINE COMPARTMENT MISSING	REPLACED MIRROR	01030008	P	8357	HR	12/07/2018	30/07/2018	13/07/2018	30/07/2018	BERGER, JOSEPH DALE
267933	MISSING TWO STEPS ON TRACK FRAME	WELDED ON NEW STEPS	01030008	P	0	HR	12/07/2018	30/07/2018	13/07/2018	30/07/2018	BRIDGES, WM S.
266880	TWO CARRIER ROLLERS LOCKED UP	REPLACED THE TWO TOP CARRIER ROLLERS ON RIGHT SIDE	01030008	F	8244	HR	25/06/2018	14/06/2018	25/06/2018	25/06/2018	COLUMBUS EQUIP CO. (PARTS & SERVICE)
266879	BACK UP ALARM INOP	REPLACED BACK UP ALARM	01030008	F	8244	HR	25/06/2018	25/06/2018	25/06/2018	25/06/2018	COLUMBUS EQUIP CO. (PARTS & SERVICE)
266875	HORN STILL INOPERATIVE	ADMINISTRATIVELY CLOSED	01030008	P	0	HR	25/06/2018	25/06/2018	25/06/2018	25/06/2018	OEDER, KYLE D.
264766	REPLACE RIGHT JOYSTICK HANDLE	Instaled new handle	01030008	P	8170	HR	22/05/2018	30/05/2018	22/05/2018	30/05/2018	DURHAM, FRANK M.
262301	TWO MIRRORS ARE BROKEN	INSTALLED 2 MIRRORS	01030008	F	0	HR	18/04/2018	23/04/2018	23/04/2018	23/04/2018	ROSENBERGER, CHRISTOPHER J.
262201	HYDRAULIC FILTER HOSES LEAKING	TIGHTENED FILTER & HOSES	01030008	F	1845	HR	16/04/2018	17/04/2018	17/04/2018	17/04/2018	LOGAN, MICHAEL A.
261547	HEAT AND A/C INOP	PLUGGED IN & TESTED	01030008	F	1842	HR	06/04/2018	09/04/2018	09/04/2018	09/04/2018	BERGER, JOSEPH DALE
245750	HYDRAULIC OIL COOLER PLUGGED	STEAMED OUT RADIATOR AND COOLERS	01030008	F	0	HR	24/07/2017	24/07/2017	24/07/2017	24/07/2017	ROBINSON, MICHAEL J.
244872	HORN INOP	REPLACED HORN/SWITCH	01030008	F	7620	HR	10/07/2017	13/07/2017	10/07/2017	13/07/2017	STOVER, JAMES MATTHEW
244871	FRONT WINDSHIELD BROKEN	INSTALLED NEW FRONT WINDSHIELD	01030008	F	7620	HR	10/07/2017	13/07/2017	13/07/2017	13/07/2017	STOVER, JAMES MATTHEW
243944	LOWER DOOR GLASS BROKEN BY A PIECE OF REBAR	REPLACED LOWER DOOR GLASS	01030008	F	7620	HR	22/06/2017	13/07/2017	13/07/2017	13/07/2017	STOVER, JAMES MATTHEW
239556	QUICK COUPLER HOSE BLOWN	REPLACED QUICK COUPLER HOSE	01030008	F	0	HR	14/04/2017	17/04/2017	14/04/2017	17/04/2017	PIRTEK READING ROAD
238571	AUXILIARY VALVE BLOCK LEAKING AT STICK	INSTALL JIC CAPS	01030008	F	6890	HR	30/03/2017	30/03/2017	30/03/2017	30/03/2017	NOBLE, KIEL JESSE
233370	WASH AND STEAM	WASHED AND STEAMED	01030008	S	6707	HR	12/12/2016	12/12/2016	12/12/2016	12/12/2016	WARREN, WILLIAM T
228647	SEAT WORN OUT	CLEANED TRASH FROM BEHIND SEAT AND LUBED SLIDES	01030008	F	6413	HR	29/09/2016	29/09/2016	29/09/2016	29/09/2016	DISNEY, WALTER RYAN
224053	REPLACE ROTOTILT SAFETY DECALS IN CAB	INSTALLED ROTO TILT SAFETY STICKERS IN CAB	01030008	0	HR	20/07/2016	05/08/2016	05/08/2016	05/08/2016	ROSENBERGER, CHRISTOPHER J.	
219506	REPAIR ACCIDENT DAMAGE TO CAB(UNSAFE TO USE UNTIL FIXED)	REPLACED CAB AND DAMAGED FRONT STEP	01030008	S	5985	HR	04/05/2016	13/06/2016	21/06/2016	21/06/2016	COLUMBUS EQUIP CO. (PARTS & SERVICE)
218669	WASH AND STEAM	WASHED AND STEAMED	01030008	S	5955	HR	20/04/2016	20/04/2016	20/04/2016	20/04/2016	ROBINSON, MICHAEL J
216694	CONNECTOR ON TOP OF STICK KEEPS COMING LOOSE	COULD NOT FIND ANY LOOSE CONNECTORS ON THE BOOM OR STICK.	01030008	S	6690	HR	15/03/2016	29/11/2016	15/03/2016	29/11/2016	PEASLEY, TYLER G
215731	REPAIR HYDRAULIC LEAK	TIGHTENED FITTING ON HOSE FOR ROTO-TILT BUCKET	01030008	S	5902	HR	25/02/2016	25/02/2016	25/02/2016	25/02/2016	GASCON, RONALD J.
211788	WASH AND STEAM	WASHED AND STEAMED	01030008	S	5876	HR	09/12/2015	09/12/2015	09/12/2015	09/12/2015	ROBINSON, MICHAEL J
211624	SUN ROOF WILL NOT LATCH SHUT	READJUSTED CATCH AND REPLACED HANDLE	01030008	S	5874	HR	07/12/2015	07/12/2015	08/12/2015	08/12/2015	GASCON, RONALD J.
211621	TWO GROUSERS ARE BENT ON RIGHT TRACK	REMOVED, STRAIGHTENED AND REINSTALLED GROUSER PADS	01030008	S	5874	HR	07/12/2015	07/12/2015	08/12/2015	08/12/2015	GASCON, RONALD J.
211620	RIGHT FRONT MIRROR IS BROKEN	REPLACED MIRROR	01030008	S	5874	HR	07/12/2015	07/12/2015	08/12/2015	08/12/2015	GASCON, RONALD J.
211619	STRAIGHTEN BENT BELLY COVERS	STRAIGHTENED 4 UNDER BELLY PANELS	01030008	S	5874	HR	07/12/2015	07/12/2015	08/12/2015	08/12/2015	GASCON, RONALD J.
211618	MISC MINOR REPAIRS	MISC/MINOR REPAIRS	01030008	S	5874	HR	07/12/2015	07/12/2015	08/12/2015	08/12/2015	GASCON, RONALD J.
211528	PM2 INSPECTION	PERFORMED PM2 INSPECTION	01030008	S	5872	HR	04/12/2015	04/12/2015	07/12/2015	07/12/2015	GASCON, RONALD J.
207390	WASH AND STEAM	WASHED AND STEAMED	01030008	S	0	HR	24/09/2015	24/09/2015	24/09/2015	24/09/2015	ROBINSON, MICHAEL J
207334	DOOR WILL NOT LATCH OPEN	READJUSTED ROLLER, LATCH CATCH, BUMPER STOPS	01030008	S	5758	HR	23/09/2015	23/09/2015	24/09/2015	24/09/2015	GASCON, RONALD J.
204978	RIGHT TRACK ROLLER IS BENT AND THE TRACK IS LOOSE	WELDED & STRAIGHTENED BRACKET	01030008	F	5696	HR	17/08/2015	17/08/2015	17/08/2015	17/08/2015	RISNER, JUSTIN A
201657	BACK UP ALARM IS NOT VERY LOUD	REPLACED BACK UP ALARM	01030008	F	0	HR	25/06/2015	30/06/2015	30/06/2015	30/06/2015	SHEEHAN, DANIEL J.
199850	AIR CONDITIONING INOP	CLEANED OUT CABIN AIR FILTER AND REPAIRED CONNECTION AT COMPRESSOR	01030008	F	5471	HR	29/05/2015	05/06/2015	05/06/2015	05/06/2015	RISNER, JUSTIN A
197060	TRACK GROUSER BENT	REMOVED & STRAIGHTENED GROUSER PAD & REINSTALLED	01030008	F	5758	HR	16/04/2015	23/09/2015	24/09/2015	24/09/2015	GASCON, RONALD J.
195942	HYDRAULIC HOSE FROM ARM TO SWIVEL HEAD ON BOOM BROKEN	REPLACED HYDRAULIC HOSE FROM ARM TO SWIVEL HEAD ON BOOM	01030008	F	0	HR	30/03/2015	31/03/2015	31/03/2015	31/03/2015	PIRTEK READING ROAD
195511	OPERATORS DOOR IS FALLING OFF	ADMINISTRATIVELY CLOSED	01030008	F	0	HR	23/03/2015	25/03/2015	24/03/2015	25/03/2015	COLUMBUS EQUIP CO. (PARTS & SERVICE)
194796	JOB START UP - CHECK OVER		01030008	S	0	HR	11/03/2015				
193053	BUCKET LINKAGE PINS AND BUSHINGS WORN OUT	ADMINISTRATIVELY CLOSED	01030008	S	0	HR	05/02/2015		13/01/2015	05/02/2015	COLUMBUS EQUIP CO. (PARTS & SERVICE)
193052	ONE TRACK FRAME STEP IS MISSING	ADMINISTRATIVELY CLOSED	01030008	S	0	HR	05/02/2015		13/02/2014	07/01/2016	COLUMBUS EQUIP CO. (PARTS & SERVICE)

189379	HIGH DIRT CAUSING HIGH IRON & ALUMINIUM IN LEFT FINAL DRIVE OIL SAMPLE RESULT	SUPER FLUSHED TWICE AND REFILLED	01030008	F	5244	HR	01/12/2014	04/12/2014	04/12/2014	04/12/2014	BERNARD, BRANDON K.
188995	WASH AND STEAM	WASHED AND STEAMED	01030008	F	0	HR	24/11/2014		24/11/2014	24/11/2014	ROBINSON, MICHAEL J
186868	HEAT IS INOP	replaced blower motor	01030008	F	5160	HR	24/10/2014	27/10/2014			BRUNS III, WILLIAM S
181850	OPERATORS DOOR WANT STAY CLOSED	REPAIRED DOOR LATCH	01030008		5248	HR	12/08/2014		13/01/2015	05/02/2015	COLUMBUS EQUIP CO (PARTS & SERVICE)
179640	cab door hard to open	REALIGNED DOOR ON TRACK	01030008	F	4815	HR	15/07/2014		15/07/2014	15/07/2014	NOBLE, KIEL JESSE
178463	air conditioning inop	REPAIRED WIRING CONNECTION AT COMPRESSOR AND RECHARGED R134	01030008	F	4780	HR	27/06/2014	02/07/2014	01/07/2014	02/07/2014	COLUMBUS EQUIP CO (PARTS & SERVICE)
176984	error code - E 02 showing - pump control system error	ADMINISTRATIVELY CLOSED	01030008	F	0	HR	11/06/2014	11/06/2014	11/06/2014	11/06/2014	WHITTINGTON, JAMES N
174462	ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030008	S	4556	HR	07/05/2014		07/05/2014	07/05/2014	GUARD, GARRETT P
171718	job start up - check over	PERFORMED JOB START UP	01030008	S	4361	HR	01/04/2014	04/04/2014	03/04/2014	04/04/2014	WHITTINGTON, JAMES N
171062	7 bad bottom rollers	REPLACED #1,2,3,9 BOTTOM ROLLERS ON LEFT AND #1,4 & 7 ON BOTTOM RIGHT	01030008	S	4230	HR	20/03/2014		20/03/2014	26/03/2014	GASCON, RONALD J.
171061	broken bolt on # 6 roller on right track	REMOVED ROLLER, REPLACED BROKEN BOLT	01030008	S	4360	HR	20/03/2014		20/03/2014	26/03/2014	GASCON, RONALD J.
171060	replace outer air filter	REPLACED OUTER AIR FILTER	01030008	S	4360	HR	20/03/2014		20/03/2014	26/03/2014	GASCON, RONALD J.
171059	replace belts	REPLACED BOTH ENGINE BELTS	01030008	S	4360	HR	20/03/2014		20/03/2014	27/03/2014	GASCON, RONALD J.
171058	misc/minor pm repairs	COMPLETED PM REPAIRS	01030008	S	4360	HR	20/03/2014		20/03/2014	27/03/2014	GASCON, RONALD J.
170837	PM2 INSPECTION	PM2 INSPECTION	01030008	S	4360	HR	18/03/2014		19/03/2014	20/03/2014	GASCON, RONALD J.
166051	NO CRANK / NO START	REPLACED BATTERIES AND REPAIRED CABLE ENDS	01030008	F	4301	HR	03/12/2013	04/12/2013	04/12/2013	04/12/2013	WHITTINGTON, JAMES N
165326	REPLACE FAN BELT	REPLACED FAN BELT	01030008	F	4298	HR	21/11/2013		20/11/2013	22/11/2013	TAYLOR, CORY R.
165325	REPLACE AIR FILTERS	REPLACED AIR FILTERS	01030008	F	4298	HR	21/11/2013		20/11/2013	21/11/2013	NOBLE, KIEL JESSE
165324	PM1 INSPECTION	PERFORMED PM1 INSPECTION	01030008	F	4298	HR	21/11/2013		20/11/2013	21/11/2013	NOBLE, KIEL JESSE
163022	WINDSHIELD WIPER IS HANGING DOWN, NEEDS REPAIRED	INSTALLED WIPER MOTOR ASSEMBLY	01030008	F	4252	HR	22/10/2013		23/10/2013	23/10/2013	NOBLE, KIEL JESSE
161881	ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030008	S	4201	HR	07/10/2013		07/10/2013	07/10/2013	GUARD, GARRETT P
155769	TOP WINDOW SHOCKS GOT RIPPED OFF	REPLACED TOP WINDOW SHOCKS	01030008	F	3966	HR	19/07/2013		23/07/2013	23/07/2013	PEASLEY, TYLER G
155605	ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030008	S	3956	HR	18/07/2013		18/07/2013	18/07/2013	GUARD, GARRETT P
151017	KOMTRAX - ERROR CODE FOR CLOGGED AIR CLEANER AGAIN	REMOVED OLD PLUGGED UP SCREEN AND REPLACED WITH NEW EXPANDED SCREEN	01030008	F	3850	HR	12/06/2013		13/06/2013	13/06/2013	GUARD, GARRETT P
150132	TRACK PAD LOOSE ON LEFT SIDE	CLEANED THE TANK GROUSER & REINSTALLED WITH NEW HARDWARE	01030008	S	3844	HR	04/06/2013		04/06/2013	04/06/2013	PEASLEY, TYLER G
150005	WASH AND STEAM	WASHED AND STEAMED	01030008	S	3838	HR	03/06/2013		03/06/2013	03/06/2013	WARREN, WILLIAM T
149868	REPAIR ACCIDENT DAMAGE TO ALL COMPARTMENT DOORS	REPAIRED COMPARTMENT DOORS	01030008	S	3838	HR	31/05/2013		03/06/2013	04/06/2013	METZ, VINCENT L.
149786	HIGH DIRT CAUSING HIGH WEAR IN LEFT FINAL OIL SAMPLE RESULTS	LAST OIL SAMPLES FOR LEFT & RIGHT FINALS WERE NORMAL	01030008	S	0	HR	30/05/2013		17/07/2013	31/07/2013	GUARD, GARRETT P
149711	WASH AND STEAM	WASHED AND STEAMED	01030008	F	3831	HR	29/05/2013		29/05/2013	29/05/2013	PHILLIPS, ADAM MICHAEL
144593	PM2 INSPECTION	PM2 INSPECTION	01030008	S	3700	HR	26/02/2013		13/02/2013	13/02/2013	COLUMBUS EQUIP CO (PARTS & SERVICE)
141150	ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030008	S	3681	HR	03/12/2012		03/12/2012	03/12/2012	GUARD, GARRETT P
140907	LEFT MIRROR BROKEN (FRAME IS GOOD)	INSTALLED NEW MIRROR ON LEFT HAND SIDE	01030008	S	3743	HR	28/11/2012		15/04/2013	15/04/2013	LOGAN, MICHAEL A.
140890	LOW ANTIFREEZE LEVEL WARNING	ADDED ANTIFREEZE	01030008	F	3672	HR	28/11/2012		28/11/2012	28/11/2012	WHITTINGTON, JAMES N
136376	ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030008	S	3406	HR	07/09/2012		07/09/2012	07/09/2012	GUARD, GARRETT P
136375	HIGH DIRT & WATER IN SWING DRIVE OIL SAMPLE		01030008	F	0	HR	07/09/2012		07/09/2012	07/09/2012	GUARD, GARRETT P
133229	REPLACE LEFT SIDE MIRROR AGAIN	INSTALLED NEW MIRROR	01030008	F	3380	HR	11/07/2012		31/08/2012	31/08/2012	RISNER, JUSTIN A
132032	ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030008	S	3114	HR	19/06/2012		19/06/2012	19/06/2012	GUARD, GARRETT P
131902	REPLACE LEFT SIDE MORROR	REPLACED MIRROR	01030008	F	3111	HR	18/06/2012		18/06/2012	18/06/2012	WHITTINGTON, JAMES N
128207	ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030008	S	2890	HR	12/04/2012		11/04/2012	11/04/2012	BERNARD, BRANDON K.
128119	ADD AUXILIARY HYDRAULICS TO MACHINE	INSTALLED HYDRAULIC KIT TO UNIT, SEE NOTES	01030008	S	0	HR	10/04/2012		10/04/2012	10/04/2012	COLUMBUS EQUIP CO (PARTS & SERVICE)
126289	RIGHT TRACK ROLLER LEAKING	REPLACED ROLLER	01030008	F	2678	HR	05/03/2012		08/03/2012	08/03/2012	DURHAM, FRANK M
124831	ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030008	S	2660	HR	03/02/2012		03/02/2012	03/02/2012	BERNARD, BRANDON K.
124268	REPLACE BATTERIES	REMOVED BATTERIES FROM 01030018 AND INSTALLED, ORDERED NEW BATTERIES	01030008	S	2652	HR	20/01/2012		20/01/2012	23/01/2012	WHITTINGTON, JAMES N
124266	JOB STARTUP	CHECKED OVER	01030008	S	2652	HR	20/01/2012		20/01/2012	20/01/2012	WHITTINGTON, JAMES N
119635	REPLACE BOTH SIDE MIRRORS	REPLACED BOTH MIRRORS	01030008	F	2417	HR	04/10/2011		04/10/2011	04/10/2011	KORNER, AARON SCOTT
114530	ERROR CODE - AIR FILTER CLOGGING	CLEANED INTAKE SCREEN	01030008	F	2074	HR	23/06/2011		23/06/2011	23/06/2011	GUARD, GARRETT P
110038	ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030008	S	2312	HR	09/03/2011		31/08/2011	31/08/2011	BERNARD, BRANDON K.
108618	PM2 INSPECTION	PERFORMED PM2 INSPECTION / REPAIRS	01030008	S	1850	HR	19/01/2011		19/01/2011	21/02/2011	COLUMBUS EQUIP CO (PARTS & SERVICE)
106451	CHECK / REPAIR VANDALISM DAMAGE FROM JOB #012593	INSTALLED 2 PIECES CUSTOMER CAB GLASS	01030008	S	1752	HR	09/11/2010	12/11/2010	09/11/2010	12/11/2010	MEL'S AUTO GLASS
104601	MISC/MINOR PM REPAIRS	INSTALLED NEW INNER & OUTER AIR FILTER & FILLED WASHER JUG	01030008	S	1676	HR	02/10/2010		02/10/2010	04/10/2010	LOGAN, MICHAEL A.
104591	PM1 INSPECTION & GREASE, CHECK ALL OILS, FUEL	PM1 INSPECTION & GREASE, CHECK ALL OILS, FUEL	01030008	S	1676	HR	01/10/2010		02/10/2010	04/10/2010	LOGAN, MICHAEL A.
103685	ANTIFREEZE CHECK	ANTIFREEZE CHECK	01030008	S	1629	HR	14/09/2010		13/09/2010	13/09/2010	BERNARD, BRANDON K.
102324	HIGH IRON, ALUMINIUM & DIRT LEVELS IN RIGHT FINAL DRIVE OIL SAMPLE	SAMPLES IMPROVED ON DIRT & IRON	01030008	S	0	HR	17/08/2010				
102323	HIGH IRON, ALUMINIUM & DIRT LEVELS IN LEFT FINAL DRIVE OIL SAMPLE	*SEE WO 149786*	01030008	S	0	HR	17/08/2010				
101356	ANTIFREEZE CHECK	ANTIFREEZE CHECK	01030008	S	1352	HR	30/07/2010		29/07/2010	29/07/2010	BERNARD, BRANDON K.
101320	ERROR CODE - AIR CLEANER CLOGGING WARNING AGAIN - SEE ALSO W/O# 97545	REMOVED AIR FILTERS, CLEANED FILTERS & AIR INTAKE SYSTEM THAT WAS CLOGGED UP	01030008	F	1350	HR	29/07/2010		29/07/2010	29/07/2010	PICKRELL, JERRY M.
97545	ERROR CODE - AIR CLEANER CLOGGING WARNING @ 1038HMR SENT FROM KOMTRAX	Cleaned screen	01030008	F	0	HR	12/05/2010	19/05/2010	12/05/2010	19/05/2010	COLUMBUS EQUIP CO (PARTS & SERVICE)
97333	ANTIFREEZE CHECK	ANTIFREEZE CHECK	01030008	S	988	HR	06/05/2010		04/05/2010	04/05/2010	GUARD, GARRETT P
93779	PM2 INSPECTION	PM2 INSPECTION	01030008	S	796	HR	26/01/2010		16/12/2009	26/01/2010	COLUMBUS EQUIP CO (PARTS & SERVICE)
92099	ANTIFREEZE CHECK	ANTIFREEZE CHECK	01030008	S	697	HR	02/12/2009		02/12/2009	02/12/2009	GUARD, GARRETT P
90520	UPDATE GPS UNIT	SWAP OUT UNIT	01030008	F	0	HR	22/10/2009		22/10/2009	22/10/2009	STILL, DWAYNE T.
89453	ANTIFREEZE CHECK	ANTIFREEZE CHECK	01030008	S	423	HR	01/10/2009		30/09/2009	30/09/2009	BERNARD, BRANDON K.
87125	STEAM RADIATOR	STEAMED RADIATOR & EQUIPMENT	01030008	F	0	HR	08/08/2009	08/08/2009	08/08/2009	08/08/2009	THOMPSON, BRAD E.
86657	ANTIFREEZE CHECK	ANTIFREEZE CHECK	01030008	S	127	HR	31/07/2009		30/07/2009	30/07/2009	BERNARD, BRANDON K.