

WO Number	WO Complaint	WO Correction	Unit ID	@	Meter Amt	Meter Type	Order Date	Deadline Date	Start Date	Complete Date	Assigned To
307468	AIR CONDITIONING INOPERATIVE	SOLD	01030026	F	0	HR	29/06/2020		26/06/2020		PURVIS, WILLIAM G.
305274	RIGHT TRACK ADJUSTER IS BLEEDING OFF	INSTALLED NEW TENSION CYLINDER	01030026	F	9085	HR	26/05/2020	10/06/2020	09/06/2020	09/06/2020	MCGLOSSON, PAUL C.
305273	AIR CONDITIONING INOPERATIVE	CLEANED OUT EVAPORATOR FINS	01030026	F	0	HR	26/05/2020	03/06/2020	26/05/2020	03/06/2020	HOLLINGSWORTH, AUSTIN
303334	BOLT FELL OUT OF "H" LINK		01030026	F	0	HR	20/04/2020	20/04/2020	20/04/2020	20/04/2020	ROWLAND, TRISTEN JAMES
301844	SEAT IS BROKEN	WELDED BROKEN TUBES ON SEAT SUSPENSION	01030026	F	8675	HR	23/03/2020	23/03/2020	23/03/2020	23/03/2020	MCGLOSSON, PAUL C.
297836	TRACK CAME OFF	REINSTALLED TRACK	01030026	F	8437	HR	06/01/2020	06/01/2020	06/01/2020	06/01/2020	DURHAM, FRANK M
293473	COUPLER SYSTEM INOP	MADE NEW HARNESS	01030026	F	0	HR	10/10/2019	10/10/2019	09/10/2019	09/10/2019	HOLLINGSWORTH, AUSTIN
292261	CHECK AIR CONDITIONING	CHARGED TO CORRECT AMOUNT AND REPLACED CABIN AIR FILTER	01030026	P	7912	HR	19/09/2019	19/09/2019	19/09/2019	19/09/2019	OLLO, JAMES EDWARD
292080	GRAB RAIL IN CAB HAS BROKEN AND MISSING BOLTS	SEE NOTES	01030026	F	7896	HR	17/09/2019	17/09/2019	17/09/2019	17/09/2019	FLANNERY, DONALD RAY
291583	REPAIR HYDRAULIC LEAK AT STICK	REPLACED BOTH ADAPTER FITTINGS IN ADAPTER BLOCKS FOR BUCKET CYLINDER	01030026	P	7896	HR	09/09/2019	17/09/2019	17/09/2019	17/09/2019	FLANNERY, DONALD RAY
290695	CAB STRUCTURE IS BREAKING AT THE GRAB RAIL	SOLD	01030026	F	0	HR	21/08/2019				
288678	A/C INOP	CLEARED DUCT WORK & CLEANED FILTERS	01030026	F	0	HR	19/07/2019	21/08/2019	21/08/2019	21/08/2019	STOVER, JAMES MATTHEW
288146	LEFT LIFT CYLINDER RETAINING PLATE FELL OFF	REINSTALLED BOLTS AND PLATE	01030026	F	7680	HR	11/07/2019	11/07/2019	11/07/2019	11/07/2019	CRAMER, NICHOLAS
287814	WASH AND STEAM COOLERS	WASH AND STEAM COOLERS	01030026	F	0	HR	06/07/2019	08/07/2019	08/07/2019	08/07/2019	SMITH, CONNOR JAMES
287804	A/C INOP	ADMINISTRATIVELY CLOSED	01030026	F	0	HR	05/07/2019	08/07/2019	05/07/2019	08/07/2019	HOLLINGSWORTH, AUSTIN
285037	WATER IN FUEL SENSOR HAS BROKEN WIRE	ADMINISTRATIVELY CLOSED	01030026	F	0	HR	20/05/2019	28/05/2019	28/05/2019	28/05/2019	WILLIS, AARON
280669	BATTERIES ARE DEAD	REPLACED BATTERIES	01030026	S	7306	HR	27/02/2019		27/02/2019	28/02/2019	COLUMBUS EQUIP CO (PARTS & SERVICE)
278519	PM2 INSPECTION	PM2 INSPECTION	01030026	F	7306	HR	14/01/2019		07/01/2019	10/01/2019	COLUMBUS EQUIP CO (PARTS & SERVICE)
278497	ROD END OF BOOM CYLINDER PIN AND BUSHINGS WORN	REPLACED BOOM ROD EYE CYLINDER PIN AND BUSHINGS	01030026	F	7306	HR	14/01/2019		14/01/2019	28/02/2019	COLUMBUS EQUIP CO (PARTS & SERVICE)
278496	MISC MINOR REPAIRS		01030026	F	7306	HR	14/01/2019		14/01/2019	28/02/2019	COLUMBUS EQUIP CO (PARTS & SERVICE)
278495	REPLACE ENGINE BELTS	REPLACED ENGINE BELTS	01030026	F	7306	HR	14/01/2019		14/01/2019	28/02/2019	COLUMBUS EQUIP CO (PARTS & SERVICE)
278493	BOTTOM SEAT CUSHION COVER TORN	REPLACED CAB SEAT BOTTOM AND COVER	01030026	F	7306	HR	14/01/2019		14/01/2019	28/02/2019	COLUMBUS EQUIP CO (PARTS & SERVICE)
276231	A TRACK PAD ON THE LEFT TRACK IS BENT	REPLACED TRACK PADS	01030026	F	7306	HR	29/11/2018		14/01/2019	28/02/2019	COLUMBUS EQUIP CO (PARTS & SERVICE)
275378	CHECK/ADJUST TRACKS	ADJUSTED TRACKS	01030026	F	7232	HR	12/11/2018	12/11/2018	12/11/2018	12/11/2018	WILLIS, AARON
272465	REPAIR HYDRAULIC LEAK	replaced blown o-ring	01030026	F	0	HR	26/09/2018	26/09/2018	26/09/2018	26/09/2018	DURHAM, FRANK M
272227	ONE STEP IS MISSING	REPLACED STEP	01030026	F	6995	HR	21/09/2018	24/09/2018	24/09/2018	24/09/2018	WILLIS, AARON
271304	TOP WINDOW FELL OUT	REAPPLIED EPOXY AND SET WINDOW IN	01030026	F	0	HR	06/09/2018	06/09/2018	06/09/2018	06/09/2018	DISNEY, WALTER RYAN
267552	A/C INOP	REPLACED WIRING AND RECHARGED A/C	01030026	F	6803	HR	05/07/2018	05/07/2018	05/07/2018	05/07/2018	WILLIS, AARON
266770	BROKEN OFF BOLT AND EXTRACTOR ON TRACK ROLLER	REPLACED BOLT	01030026	F	7306	HR	22/06/2018		14/01/2019	28/02/2019	COLUMBUS EQUIP CO (PARTS & SERVICE)
266378	3 TRACK ROLLERS LEAKING, MARKED WITH PAINT	REPLACED TRACK ROLLERS	01030026	F	6775	HR	15/06/2018	22/06/2018	15/06/2018	22/06/2018	WILLIS, AARON
262853	REPAIR PLAY IN BUCKET LINKAGE	INSTALLED NEW BUCKET PINS, BUSHINGS AND HARDWARE	01030026	S	6631	HR	25/04/2018		05/04/2018	25/04/2018	COLUMBUS EQUIP CO (PARTS & SERVICE)
262852	MISC MINOR REPAIRS	MISC MINOR REPAIRS	01030026	S	6631	HR	25/04/2018		05/04/2018	25/04/2018	COLUMBUS EQUIP CO (PARTS & SERVICE)
262851	REPLACE ENGINE BELTS	REPLACED ENGINE BELTS	01030026	S	6631	HR	25/04/2018		05/04/2018	25/04/2018	COLUMBUS EQUIP CO (PARTS & SERVICE)
259766	PM2 INSPECTION	PERFORMED PM 2 INSPECTION	01030026	F	6631	HR	07/03/2018		01/03/2018	05/03/2018	COLUMBUS EQUIP CO (PARTS & SERVICE)
249364	HYDRAULIC FUNCTIONS SAFETY LEVER INOP AT TIMES	NO CORRECTION MADE/OPERATOR ERROR	01030026	F	6380	HR	16/09/2017	15/09/2017	15/09/2017	15/09/2017	STOVER, JAMES MATTHEW
248379	TRAVEL ALARM STUCK	REPLACED ALARM	01030026	F	6332	HR	31/08/2017	31/08/2017	31/08/2017	31/08/2017	BERGER, JOSEPH DALE
248336	CHECK/ADJUST TRACKS	CHECKED TENSION AND CHECKED SWING DRIVE OIL	01030026	F	6332	HR	30/08/2017	31/08/2017	31/08/2017	31/08/2017	BERGER, JOSEPH DALE
248335	HYDRAULIC LEAK @ BUCKET TILT CYLINDER	REPLACED ORINGS IN HOSE GOING TO BLOCK ON BUCKET TILT CYLINDER	01030026	F	6326	HR	30/08/2017	30/08/2017	30/08/2017	30/08/2017	DISNEY, WALTER RYAN
247531	BOLTS BROKE OUT OF VALVE BLOCK ON STICK	REMOVE BROKEN & REPLACE BOLTS	01030026	F	6823	HR	18/08/2017		18/08/2017	18/08/2017	RISNER, JUSTIN A
245164	RIGHT STEP IS MISSING	WELDED ON NEW STEP	01030026	F	6203	HR	14/07/2017	18/07/2017	18/07/2017	18/07/2017	BARKER JR, WILLIAM T.
240567	LEFT FINAL MOTOR PLATE COVER THREADED MOUNTING TAB BROKEN	CUT NEW TAB, DRILLED AND TAP AND WELDED INTO POSITION	01030026	F	6035	HR	01/05/2017		12/06/2017	12/06/2017	MCGLOSSON, PAUL C.
240503	FOUR TRACK ROLLERS LEAKING OIL	REPLACED LEAKING ROLLERS	01030026	F	6035	HR	28/04/2017		12/06/2017	12/06/2017	MCGLOSSON, PAUL C.
240502	UPPER CLAMP ON BUCKET CYLINDER BENT	REPLACED CLAMP	01030026	F	6035	HR	28/04/2017		12/06/2017	12/06/2017	MCGLOSSON, PAUL C.
240367	WINDSHIELD WASHER INOP	CLEANED OUT LINES	01030026	F	5904	HR	27/04/2017		27/04/2017	27/04/2017	OEDER, KYLE D.
240366	2 BROKEN BOLTS ON TWO DIFFERENT TRACK ROLLERS	WELDED OUT BROKEN BOLTS, INSTALLED NEW	01030026	F	6035	HR	27/04/2017		12/06/2017	12/06/2017	MCGLOSSON, PAUL C.
240365	ONE CAB WORK LIGHT INOP	REPLACED BLUB	01030026	F	5904	HR	27/04/2017		28/04/2017	28/04/2017	MCGLOSSON, PAUL C.
240364	MISSING BATTERY COVER AND HOLD DOWN KNOBS	REPLACED	01030026	F	5904	HR	27/04/2017		28/04/2017	28/04/2017	MCGLOSSON, PAUL C.
240363	INSTALL MISSING FIRE EXTINGUISHER	INSTALLED NEW FIRE EXTINGUISHER	01030026	F	5904	HR	26/04/2017		27/04/2017	27/04/2017	OEDER, KYLE D.
240362	H-LINK CYLINDER BARREL END HOSE SHOWING STEEL LEFT SIDE OF BOOM	REPLACED HOSE	01030026	F	5904	HR	26/04/2017		28/04/2017	28/04/2017	MCGLOSSON, PAUL C.
235898	REPLACE BROKEN SPOT MIRROR	REPLACE BROKEN SPOT MIRROR	01030026	F	5672	HR	06/02/2017	10/02/2017	10/02/2017	10/02/2017	DURHAM, FRANK M
235881	HYDRAULIC LEAK IN BELLY PAN AREA	replace o-rings i hyd hoses	01030026	F	5672	HR	06/02/2017	07/02/2017	06/02/2017	07/02/2017	DURHAM, FRANK M
234110	STEP FOR STAIRS BENT/WELDS CRACKED	strigten steps	01030026	F	0	HR	03/01/2017	07/02/2017	07/02/2017	07/02/2017	DURHAM, FRANK M
234108	REPLACE BOTH CAB AIR FILTERS	REPLACED FILTERS	01030026	F	5670	HR	03/01/2017		06/01/2017	06/01/2017	MCGLOSSON, PAUL C.
234105	WIPER ARM BROKEN FOR FRONT MAIN WINDOW	REPLACED WIPER ARM	01030026	F	0	HR	03/01/2017	10/02/2017	07/02/2017	10/02/2017	DURHAM, FRANK M
234104	STEAM UNDERCARRIAGE	SCRAPED OUT TRACKS AND WASHED AND STEAMED	01030026	F	5803	HR	03/01/2017		07/04/2017	07/04/2017	DEUFEMIA, ROCCO
234102	PM2 INSPECTION	PERFORMED PM2 INSPECTION	01030026	F	5904	HR	03/01/2017		03/01/2017	27/04/2017	MCGLOSSON, PAUL C.
227591	CANNOT GET LIGHT & BUZZER TO COME ON FOR BUCKET RELEASE	REPAIRED COUPLER WIRING	01030026	F	5183	HR	12/09/2016		12/09/2016	12/09/2016	PHILLIPS, ADAM MICHAEL
226163	HYDRAULIC LEAK IN FRAME UNDER COUNTERWEIGHT	TIGHTENED FITTINGS WITH NEW O-RINGS	01030026	F	5117	HR	19/08/2016		20/08/2016	20/08/2016	BERGER, JOSEPH DALE
225462	HYD. LEAK @ TURNABLE	TIGHTEN LOOSE FITTINGS	01030026	F	5088	HR	09/08/2016		09/08/2016	09/08/2016	RISNER, JUSTIN A
213208	REPAIR HYDRAULIC LEAK AT SWIVEL	REPLACED O-RINGS	01030026	P	4726	HR	07/01/2016		17/12/2015	29/12/2015	COLUMBUS EQUIP CO (PARTS & SERVICE)
213207	3 LOWER TRACK ROLLERS LEAKING	REPLACED 3 BOTTOM ROLLERS	01030026	P	4726	HR	07/01/2016		07/01/2016	07/01/2016	COLUMBUS EQUIP CO (PARTS & SERVICE)
213206	MISC MINOR REPAIRS	MISC MINOR REPAIRS	01030026	P	4726	HR	07/01/2016		07/01/2016	07/01/2016	COLUMBUS EQUIP CO (PARTS & SERVICE)
213205	REPLACE ENGINE BELTS	REPLACED ENGINE BELTS	01030026	P	4726	HR	07/01/2016		07/01/2016	07/01/2016	COLUMBUS EQUIP CO (PARTS & SERVICE)
213119	BAD HYDRAULIC LEAK AT SWING MOTOR	REMOVED HOSES AND FITTINGS, REPLACED O-RINGS AND REINSTALLED	01030026	P	4735	HR	06/01/2016		06/01/2016	06/01/2016	MCGLOSSON, PAUL C.
212425	PM2 INSPECTION	PERFORMED PM2 INSPECTION	01030026	S	4726	HR	17/12/2015		15/12/2015	17/12/2015	COLUMBUS EQUIP CO (PARTS & SERVICE)
205004	HYDRAULIC LEAK UNDER MACHINE WHEN TRAVELING	INSTALLED NEW O-RINGS & REINSTALLED FITTINGS	01030026	F	4315	HR	17/08/2015		18/08/2015	18/08/2015	STOVER, JAMES MATTHEW
204230	TWO BOTTOM TRACK ROLLERS LEAKING BADLY	REPLACED ROLLERS MARKED WITH PAINT	01030026	F	4265	HR	05/08/2015		12/08/2015	12/08/2015	BRUNS III, WILLIAM S
201484	ENGINE GETTING HOT	STEAMED OFF RADIATOR & REPLACED AIR FILTERS	01030026	S	0	HR	22/06/2015		22/06/2015	22/06/2015	OEDER, KYLE D.
200995	WASH AND STEAM MACHINE, RADIATOR AND COOLERS	ADMINISTRATIVELY CLOSED	01030026	F	0	HR	16/06/2015	16/06/2015	16/06/2015	16/06/2015	ERKENBRECHER, ANDREW
200547	RIGHT SIDE CAB MIRROR NEEDS REPLACED	REPLACED MIRROR	01030026	F	3978	HR	09/06/2015		16/06/2015	16/06/2015	RUTHER, MATTHEW
199798	TWO TRACK ROLLERS LEAKING, ONE ON EACH SIDE (MARKED WITH PINK PAINT)	REPLACED 1 ROLLER ON THE RIGHT & 1 ROLLER ON THE LEFT	01030026	F	3898	HR	28/05/2015		02/06/2015	02/06/2015	PEASLEY, TYLER G
197964	BUCKET CYLINDER IS LEAKING HYDRAULIC OIL	RESEALED BUCKET CYLINDER	01030026	F	6631	HR	30/04/2015		03/04/2018	25/04/2018	COLUMBUS EQUIP CO (PARTS & SERVICE)
197796	BACK UP ALARM IS INOP	REPLACED BACK UP ALARM	01030026	F	3751	HR	28/04/2015		28/04/2015	28/04/2015	PEASLEY, TYLER G
195674	WASH AND STEAM	WASH AND STEAM	01030026	S	8286	HR	25/03/2015	26/03/2015	25/03/2015	25/03/2015	ERKENBRECHER, ANDREW
195047	NO CRANK / NO START	JUMP STARTED, checked charging system	01030026	S	3536	HR	17/03/2015		17/03/2015	17/03/2015	SINGER, GREG LEE
194015	JOB START UP - CHECK OVER	PERFORMED JOB START UP	01030026	S	3536	HR	24/02/2015		17/03/2015	17/03/2015	SINGER, GREG LEE
193745	REPAIR BUCKET COUPLER CONTROL VALVE MOUNTS AND HOSE KEEPERS	Installed Control Valve Assembly With Cover And Secured All Hoses	01030026	S	3531	HR	17/02/2015		30/01/2015	17/02/2015	COLUMBUS EQUIP CO (PARTS & SERVICE)
193744	REPAIR RIGHT FRONT STEP	Replaced Right Front Step	01030026	S	3531	HR	17/02/2015		30/01/2015	17/02/2015	COLUMBUS EQUIP CO (PARTS & SERVICE)
193743	REPLACE ENGINE BELTS	REPLACED ENGINE BELTS	01030026	S	3531	HR	17/02/2015		30/01/2015	17/02/2015	COLUMBUS EQUIP CO (PARTS & SERVICE)
192570	PM2 INSPECTION	PM2 INSPECTION	01030026	S	3531	HR	28/01/2015		06/01/2015	06/01/2015	COLUMBUS EQUIP CO (PARTS & SERVICE)
190818	wash and steam	WASH AND STEAM	01030026	S	3410	HR	05/01/2015		05/01/2015	06/01/2015	ROBINSON, MICHAEL J
188326	REPAIR BROKEN HYDRAULIC FITTING AT QUICK DISCONNECT VALVE BLOCK	REPLACED FITTING IN STICK VALVE	01030026	F	0	HR	13/11/2014		13/11/2014	13/11/2014	ROSENBERGER, CHRISTOPHER J.

188140 wash and steam	WASHED AND STEAMED	01030026 F	3396 HR	12/11/2014	12/11/2014	12/11/2014	12/11/2014 ROBINSON, MICHEAL J
188045 quick coupler lock will not unlock	REPAIR WIRING	01030026 F	0 HR	11/11/2014		11/11/2014	11/11/2014 ROSENBERGER, CHRISTOPHER J.
184327 REPLACE DEAD BATTERIES	CHECK AND REPLACED BATTERIES	01030026 F	0 HR	16/09/2014		16/09/2014	16/09/2014 ROSENBERGER, CHRISTOPHER J.
181785 SAFETY LATCH ON BUCKET QUICK DISCONNECT IS LOOSE	REPLACED BOLTS IN SAFETY LATCH	01030026 F	3005 HR	12/08/2014		12/08/2014	12/08/2014 ROSENBERGER, CHRISTOPHER J.
181784 HYDRAULIC LEAK ON STICK	REPLACED O-RING ON LOOSE HYDRAULIC HOSE	01030026 F	3005 HR	12/08/2014		12/08/2014	12/08/2014 ROSENBERGER, CHRISTOPHER J.
181476 HYDRAULIC LEAK NEAR CENTER OF MACHINE	replaced o-ring on fitting on top of swivel	01030026 F	0 HR	08/08/2014		08/08/2014	09/12/2014 ROSENBERGER, CHRISTOPHER J.
178580 ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030026 S	2654 HR	30/06/2014		28/06/2014	28/06/2014 BERNARD, BRANDON K.
177111 HORN INOP	REPLACED HANDLE ON HORN SWITCH	01030026 F	2753 HR	12/06/2014		12/06/2014	13/06/2014 ROSENBERGER, CHRISTOPHER J.
176905 ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030026 S	2451 HR	10/06/2014		06/06/2014	06/06/2014 BERNARD, BRANDON K.
176882 remount valve block on stick	MOUNTED VALVE BLOCK BACK ON STICK	01030026 F	2451 HR	10/06/2014		10/06/2014	10/06/2014 ROSENBERGER, CHRISTOPHER J.
176881 repair blown hydraulic hose on stick	REPLACED BLOWN HOSE	01030026 F	2451 HR	10/06/2014		10/06/2014	10/06/2014 ROSENBERGER, CHRISTOPHER J.
170329 repair / replace steps	WELDED NEW STEP ON LEFT FRONT AND STRAIGHTENED RIGHT FRONT STEP	01030026 S	1900 HR	11/03/2014		11/03/2014	11/03/2014 GASCON, RONALD J.
170328 right side boom light inop	REPLACED BULB	01030026 S	1900 HR	11/03/2014		11/03/2014	11/03/2014 GASCON, RONALD J.
170241 pm2 inspection	PM2 INSPECTION	01030026 S	1900 HR	10/03/2014		10/03/2014	11/03/2014 GASCON, RONALD J.
169295 WASH AND STEAM	WASHED AND STEAMED	01030026 S	1898 HR	19/02/2014		19/02/2014	19/02/2014 PHILLIPS, ADAM MICHAEL
166782 ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030026 S	1825 HR	16/12/2013		16/12/2013	16/12/2013 GUARD, GARRETT P
165126 ACCIDENT DAMAGE	REPAIRED ACCIDENT DAMAGE AND PAINTED	01030026 S	1899 HR	18/11/2013		18/02/2014	25/02/2014 METZ, VINCENT L.
162971 HYDRAULIC LEAK ON TOP OF ROTO COUPLER	TIGHTENED JAM NUT	01030026 F	1716 HR	22/10/2013		22/10/2013	01/11/2013 PURVIS, WILLIAM G.
158376 ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030026 S	1563 HR	20/08/2013		20/08/2013	20/08/2013 GUARD, GARRETT P
158270 LOWER FRONT WINDOW AND HANDLES MISSING	REPLACED LOWER GLASS	01030026 F	1564 HR	19/08/2013		23/08/2013	23/08/2013 PURVIS, WILLIAM G.
149406 ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030026 S	1268 HR	23/05/2013		22/05/2013	22/05/2013 GUARD, GARRETT P
146223 LEFT REAR CAB WINDOW SEAL IS NOT HOLDING ANYMORE	INSTALLED SEAL KIT ON LEFT REAR WINDOW	01030026 F	0 HR	09/04/2013		10/04/2013	10/04/2013 MEL'S AUTO GLASS
143629 LEFT REAR SIDE WINDOW SHATTERED	REPLACED WITH OEM GLASS & DOUBLE STICK SEAL	01030026 F	1091 HR	01/02/2013		26/02/2013	26/02/2013 PURVIS, WILLIAM G.
141005 ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030026 S	5334 HR	29/11/2012		27/11/2012	27/11/2012 GUARD, GARRETT P
137260 ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030026 S	710 HR	24/09/2012		24/09/2012	24/09/2012 GUARD, GARRETT P
133718 ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030026 S	424 HR	19/07/2012		19/07/2012	19/07/2012 GUARD, GARRETT P
130397 ANTIFREEZE CHECK	ANTIFREEZE CHECKED	01030026 S	161 HR	18/05/2012		17/05/2012	17/05/2012 BERNARD, BRANDON K.
127896 NEW EQUIPMENT SET-UP	NUMBERED, DECALED AND INSTALLED FUEL RING	01030026 S	0 HR	05/04/2012		05/04/2012	06/04/2012 SINGLETON, GREG L.