

SANDVIK QI 341-10052 Impact Crusher Service and Replacement Record

February 2024	Installed new Blocks that support and hold all 4 Impact Hammers in place	
June 2024	full equipment service	
June 2024	New Main Pump and New Main Pump Clutch installed, this operates and moves the vibration motor for crushing mechanism and moves side belts	
July 2024	Installed 2 New Impact Hammers	
August 2024	Installed New Main Hydraulic Pump Drive Shaft #2 left side, this operates the hammer system	
December 2024	full equipment service	