

User: Matcek, Randal J.

Created Date: May 18, 2026

Serial Number: M9C00224

Product Family: MOTOR GRADER

Model: 120M2

SMU / Hours:

Year: 2012

SERVICE HISTORY (31 Records)

Invoice Date	Invoice Type	SMU / Hours	Description	Notes
Apr 24, 2026	Parts			
Apr 24, 2026	Parts			
Oct 22, 2025	Parts			
Oct 22, 2025	Parts			
Apr 24, 2025	Parts			
Apr 23, 2025	Parts			
Dec 23, 2024	Parts			
Nov 27, 2024	Parts			
Oct 02, 2024	Parts			
May 08, 2024	Parts			
Apr 29, 2024	Parts			
Apr 23, 2024	Parts			
Mar 31, 2023	Service	2,570	Transport Machine	Trk54- d&w contractors
Aug 19, 2020	Parts			
Mar 18, 2020	Parts			
Jul 02, 2019	Service	2,436	Prepare For Waty Prod Support Prog (psp)	Ps46189
Jul 02, 2019	Service	2,436	Prepare For Waty Prod Support Prog (psp)	Ps46189

May 24, 2019	Service	2,381	Troubleshoot Steering System	Codes for steering
May 24, 2019	Service	2,381	Repair Wiring Harness	Installed new resistors
May 24, 2019	Service	2,381	Travel To/from Machine	15831 miller road 1, houston tx
Jun 08, 2017	Service	2,063	Prepare For Waty Prod Support Prog (psp)	Ps53408
Jun 08, 2017	Service	2,063	Prepare For Waty Prod Support Prog (psp)	Ps53408
Jun 08, 2017	Service	2,063	Troubleshoot Engine	Repair machine Troubleshooting time not covered under Service letter to replace fan asy.
Jun 08, 2017	Service	2,063	Travel To/from Machine	Witter street and jackson in pasadena
Jun 06, 2017	Service	2,060	Perform Pm 1	Pm1 with zone charge Garner and shaver Ellizar 713-823-0428
Nov 17, 2016	Service	1,925	Travel To/from Machine	Randolph & spensor Pasadena tx
Nov 17, 2016	Service	1,925	Troubleshoot Machine	Low voltage
Apr 19, 2016	Service	1,829	Troubleshoot Machine	Customer complaint: 02-replace wear strips Repair process comments: 02-replace wear strips. went out to the job and Checked out wear strips. went to the shop and Ordered the strips. the customer set up a repair Date, went out and it was raining. waited for it To quit and it did not. went out the next day and Removed the side plates on top and bottom. Removed the top wear plater, the bottom were Gone. dug hard and packed mud. i called scott Ryan for some help. we got all the dirt out and Installed new wear strips. installed the side Plates and bolted in place. adjusted the wear Strips. note! the wear strips will not last. the 265108.0 mount gp blade is wore. this holds the Strip in place. the mount gp is wore 1/4 of a Inch. there is a 1/4 in gap between the wear Strip and the mount gp. this needs to be Corrected. don pratorius #0284. Wear strips on cutting edge need to be replaced

Apr 19, 2016	Service	1,829	Travel To/from Machine	Beltway 8 and tc jester
Mar 18, 2016	Service	1,793	Perform Pm 3	Tc jester north of beltway 8 past gears rd Pm 3 with zone 1 charge Keith 281-808-0621
Jan 31, 2016	Parts			