


D17



3130 St. Rte. 18
Norwalk, Ohio, 44857

419-663-2457


REPAIR ORDER

SERVICE MACHINE

TIME PROMISED		AM ☐	PM ☐
YR. 12	MAKE JOHN DEERE	DATE 9/4/2020	
MODEL 700 K	WRITTEN BY KASEY		
LICENSE	MOTOR NO. D17		
PIV. NO.	SPEEDOMETER 3085HR		

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Signed



3130 St. Rte. 18

Norwalk, Ohio, 44137

419-663-2457

REPAIR ORDER

changed oil / Filter

TIME PROMISED		AM ☐	PM ☐
TH	MAKE	DATE	
MODEL		3/16/20	
LICENSE		WRITTEN BY	
PIA. NO.		John	
		MOTOR NO.	
		SPEEDOMETER	
		19234R	

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Signed

Eloned



JOHN DEERE

Packing list

Ship-to party 10037360
MARK HAYNES CONSTRUCTION INC
3130 STATE ROUTE 18
NORWALK OH 44857

Forwarding agent

Shipment No.:
Delivery No.: 82008941
Delivery Date: 10/16/2019

Sold-to party 99999PTY00
JD Merchandise
JDM DIV, DEERE MKT SERV
1600 First Avenue East
MILAN IL 61264

Shipping point SSE1
John Deere Reman - Springfield
4500 E MUSTARD WAY
SPRINGFIELD MO 65803-7135



Seal No.:
Total Gross Weight: 768.234 KG
Total Gross Volume:
DNS Order Number: DY00739466
B/L Number:

Terms of Delivery:
Shipping Instructions:


Payment Terms: Y11M I/C - 1st of 2nd month following shipment

Shipping conditions: 71 UPS Ground

Level	Identification PO Number Legacy Order	SO Item	Material / Customer Material Description Item Note/Serial Number/Contents	Quantity	Weight Length	Volume Width Returnable	Height Hazardous
	559698 P89045TY	000010	SE502830 / SE502830 ENGINE, COMPLETE 6068 IT4	1 PC	768.234 KG		
			SE6068R001084				

6861569

XPOLogistics



584-612383

DIT

D17

FLUID ANALYSIS

UIN 078CAF3

Diesel Engine

Unit No. 1T0750JXLBD209705

Unit:
Make John Deere
Model 750J
Serial No. 1T0750JXLBD209705

ite

Compartment:

Name Diesel Engine
Make
Model
Serial No.
Capacity: 0.0 Ltrs

Customer:

MARK HAYNES CONSTRUCTION
3130 State Route 18
Norwalk OH 44807
USA

DIAGNOSIS

No recommended action at this time. Resample at normal intervals.

DATE SAMPLED	02-Oct-19
DATE RECEIVED	15-Oct-19
DATE REPORTED	16-Oct-19

LAB NO.	41022314378
SIF NO.	35280149
TIME ON UNIT	Hrs 2829
TIME ON OIL	Hrs 103
OIL BRAND	Shell
OIL TYPE	Unidentified
OIL GRADE	SAE 15W40
OIL ADDED	
FILTER	Not Applicable
OIL CHANGED	Not Changed
WO NUMBER	

Metals (ppm)

Iron (Fe)	20
Chromium (Cr)	<1
Lead (Pb)	<1
Copper (Cu)	3
Tin (Sn)	1
Aluminium (Al)	5
Nickel (Ni)	<1
Silver (Ag)	<1
Titanium (Ti)	<1
Vanadium (V)	<1

Contaminants (ppm)

Silicon (Si)	8
Sodium (Na)	6
Potassium (K)	5
Water (%)	<0.05
Coolant	No
Fuel (%)	<1
Soot (%) Infrared	0.2

Additives (ppm)

Magnesium (Mg)	75
Calcium (Ca)	2285
Barium (Ba)	<1
Phosphorus (P)	1031
Zinc (Zn)	1257
Molybdenum (Mo)	11
Boron (B)	189

Physical Tests

Viscosity (cSt 100C)	13.4
----------------------	------

Physical / Chemical

Base Number (mgKOH/g)	4.9
-----------------------	-----




ANALYST: Sam Smith Cleveland

LEGEND			
Normal	Severe	Abnormal	Caution
Normal			Normal

FLUID ANALYSIS

UIN 078CAF3



Since services are based on samples and information supplied by others, and since corrective actions, if any, are necessarily taken by others, these services are rendered without any warranty or liability of any kind beyond the actual amount paid to ALS Tribology for the services. Reported recommendations are based on interpretations of the generated test results and historical data. Certain test results appearing in this report may have been tested at other ALS laboratories within the Tribology divisional network.

Mark Haynes Construction
Attn: Mike Martz
3130 State Route 18
Norwalk OH 44807
USA

0003 v1.5

U.S. Laboratories

Atlanta, Georgia - 420 Valley View, Ohio - 410

3121 Presidential Drive
Atlanta, GA 30340
800.394.3669

6180 Halle Dr. Suite D
Valley View, OH 44125
800.726.5400

Kansas City, Kansas - 430 Phoenix, Arizona - 440

935 Sunshine Road
Kansas City, KS 66115
800.332.8055

3319 West Earl Drive
Phoenix, AZ 85017
800.445.7930

Portland, Oregon - 401

4943 NW Front Avenue
Portland, OR 97210
800.770.4128

Canadian Laboratories

Burlington, Ontario - 450 Edmonton, Alberta - 402

5036 South Service Rd.
Burlington, ON L7L5Y7
905.332.9559

10717-176 Street
Edmonton, AB T5S 1K1
888.489.0057

Sales & Marketing

Houston, Texas

10450 Standiff Road, Suite 210
Houston, TX 77099
877.835.8437

International Locations

Australia

Brisbane, Perth, Sydney, Muswellbrook

South America

Santiago de Chile, Belo Horizonte, Brazil

New Zealand

Wellington

Southeast Asia

Kuala Lumpur, Singapore

Europe

Prague

TEST METHODS:

Acid Number:	ASTM D974/D664 (*M)
Base Number:	ASTM D4739 (*M)
Base Number (Perchloric):	ASTM D2896 (*M)
Fuel Dilution by GC:	ASTM D7593
Fuel Dilution Visc/Setflash	In House
Fuel Soot ATR/IR:	ASTM D7686 (*M)
Soot by FTIR:	ASTM D7844
Glycol:	In House
Metals by ICP AES:	ASTM D5185 (*M)
Ox, NOx, SOx, FTIR:	ASTM D7418/D7414/D7415 D7624
PQ Index:	ASTM D8120 (*M)
Particle Count:	ASTM D7647 (*M) / ISO 4406
Viscosity:	ASTM D445 (*M) / D7279 (*M)
Water KF:	D6304C / E203 (*M)
Water Crackle:	In House

*M - Modified Method

FLUID ANALYSIS

Fuel Sample Analysis

MARK HA' CONSTRUCTION
3130 State Route 18
Norwalk OH 44807
USA

UIN: 078C957 Serial No.: 1T0750JXLBD209705
Fuel Type: Diesel Fuel Site:
Tank ID: 1T0750JXLBD209705

Compartment Name: Diesel Fuel
Fuel Manufacturer: Unidentified
Fuel Type: Diesel Fuel #1
Tank Capacity:
Hours After Refueling:

Date Sampled: 02-Oct-19
Date Received: 15-Oct-19
Date Reported: 18-Oct-19
Lab No.: 41022314493
WO No.:
SIF No.: 36284731

TEST/METHOD

RESULTS

UNITS

Metals (ppm)		
Lead (Pb)	<1	ppm
Copper (Cu)	<1	ppm
Tin (Sn)	<1	ppm
Contaminants (ppm)		
Silicon (Si)	<1	ppm
Sodium (Na)	<1	ppm
Distillation (ASTM D86)		
Initial Boiling Point	330	°F
10% Recovered	400	°F
50% Recovered	509	°F
90% Recovered	609	°F
End Point	655	°F
% Recovered	98.0	Volume %
Additives (ppm)		
Zinc (Zn)	<1	ppm
Magnesium (Mg)	<1	ppm
Calcium (Ca)	<1	ppm
Potassium (K)	<1	ppm
Physical / Chemical		
API Gravity @60F (D287/D1298)	34.4	° API
Calculated Cetane Index (D4737)	44.4	CCI
Total Particulate (D5452/D6217C/D7321)	1.0	mg/L
Water by Karl Fischer ppm (E203/D6304)	79	ppm
Sulfur (D5453/D7039/D4294)	8	ppm
Water by Distillation (D95)	<0.1	Volume %
Biodiesel Blend Content (ALS 2001)	1.0	Volume %
Cold Filter Plugging Point (IP309/D6371)	-9	°F
Additional		
Appearance	1	

Appearance Key:

- 1 = Bright and Clear, No particulate
- 2 = Trace Free Water
- 3 = Trace particulate or sediment
- 4 = Moderate particulate and/or free water
- 5 = Heavy particulate and/or free water

ANALYST: Ed.Eckert



Normal

LEGEND



Severe



Abnormal



Caution



Normal

DIAGNOSIS:

Sample appears clear and bright with no visible particulate or free water. Test results are within ASTM specifications for #2 S15 ultra low sulfur diesel fuel.

Since services are based on samples and information supplied by others, and since corrective actions, if any, are necessarily taken by others, these services are rendered without any warranty or liability of any kind beyond the actual amount paid to ALS Tribology for the services. Reported recommendations are based on interpretations of the generated test results and historical data. Certain test results appearing in this report may have been tested at other ALS laboratories within the Tribology divisional network.

HOW TO CONTACT US

U.S. Laboratories

Atlanta, Georgia

3121 Presidential Drive
Atlanta, GA 30340
800.394.3669

Valley View, Ohio

6180 Halle Dr. Suite D
Valley View, OH 44125
800.726.5400

Kansas City, Kansas

935 Sunshine Road
Kansas City, KS 66115
800.332.8055

Phoenix, Arizona

3319 West Earll Drive
Phoenix, AZ 85017
800.445.7930

Portland, Oregon

4943 NW Front Avenue
Portland, OR 97210
800.770.4128

Canadian Laboratories

Burlington, Ontario

5036 South Service Rd.
Burlington, ON L7L5Y7
+1 905 332 9559

Edmonton, Alberta

10717-176 Street
Edmonton, AB T5S 1K1
888.489.0057

Sales & Marketing

Houston, Texas

10450 Stancliff Road, Suite 210
Houston, TX 77099
877.835.8437

International Locations

Europe

Prague

Australia

Brisbane, Perth, Sydney, Muswellbrook

New Zealand

Wellington

South America

Santiago de Chile
Belo Horizonte, Brazil

Southeast Asia

Kuala Lumpur, Singapore

Mark Haynes Construction
Attn: Mike Martz
3130 State Route 18
Norwalk OH 44807
USA

P17



Murphy Tractor & Equipment Co., Inc.
 2121 Walcutt Rd
 Columbus, OH 43228
 Phone: 614-876-1141
 Toll Free: 800-222-2010
 Fax: 614-876-3059



Invoice To Account No: 18006235

Deliver To:

SERVICE INVOICE

MARK HAYNES CONSTRUCTION INC PRESIDEN MARK HAYNES 3130 SR 18 NORWALK OH 44857	MARK HAYNES CONSTRUCTION INC 3130 SR 18 NORWALK OH 44857	Invoice Number: 1233145 Invoice Date: 9/16/2019 Location: 18 Work Order Number: 269660 Payment Type: Finance
Bus Phone: 4196634457 Prv Phone:	Bus Phone: 4196634457 Prv Phone:	Page: 1 of 2

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 700K	3295	1T0700KXLC231891	SR700K	

/Travel - 1 Retail
 COMPLAINT:
 richenbacker golf course
 cody Hill 740-541-2948

CORRECTION:
 richenbacker golf course
 cody Hill 740-541-2948

49 MILES > 9/11/19
 49 MILES > 9/13/19
 53 MILES > 9/13/19

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SVCTRUCK	MILEAGE CHARGE	98.00	3.50	3.50	\$343.00	Y
Labor: \$330.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$343.00	Sub-Total: \$673.00	

Gen1- Retail
 COMPLAINT:
 engine quit running, while trying to start sounds like there is no compression

CORRECTION:
 engine quit running, while trying to start sounds like there is no compression.

9/11/19 > FOUND NO ACTIVE CODES, ENGINE WOULD NOT START, CHECK FUEL PRESSURE ALL OK, REMOVE VALVE COVER DID NOT SEE ANY BROKEN PARTS.

9/13/19 > RETURN TO MACHINE AND RUN A COMPRESSION TEST AND FOUND #4 CYLINDER DID NOT HAVE ANY COMPRESSION, OTHER CYLINDERS WERE IN SPECS.

OWNER TO TAKE MACHINE TO THERE SHOP AND MAKE NEEDED REPAIRS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------



3130 St. Rte. 18

Norwalk, Ohio, 44857

419-663-2457

REPAIR ORDER

QTY	PART NO.	DESCRIPTION	EACH AMOUNT
1	T223520	Left corner bit	
1	T223519	Right corner bit	
12	T178085	Shims	
6	T177876	Shims	
4	T177309	Shims	
2		Idlers	
2		Pistons & band for Idler	

Turned center cutting edge, new corner bits.

replaced both Idlers & adjusting rods

TIME PROMISED		AM ☐ PM ☐	
DATE	MAKE	DATE	
MODEL	760K	8-5-79	
LICENSE		METER NO.	
PR. NO.	D17	SPEEDOMETER	
		2787.6	

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An Express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Signed



3130 St. Rte. 18

Norwalk, Ohio, 44857

419-663-2457

REPAIR ORDER

Serviced

Due at 3066

TIME PROMISED		A.M. ☐	P.M. ☐
TH.	WAGE	DATE	
MODEL		WRITTEN BY	
LICENCE		Unknown	
MOTOR NO.		MOTOR NO.	
M.O. NO. D17		SPEEDOMETER	
		2766	

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Signed

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An approved Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.



3130 St. Rte. 18

Norwalk, Ohio, 44857

419-668-2457

D-17

QTY	PART NO.	DESCRIPTION	SALE AMOUNT
-----	----------	-------------	-------------

1	AT 925334	linkage	
---	-----------	---------	--

REPAIR ORDER

TIME PROMISED		AM. ☐	PM. ☐
YR.	MAKE	DATE	
	Deere	8-27-78	
MODEL	700	WRITTEN BY	
		C. H. H.	
LICENSE		MOTOR NO.	
PO. NO.		SPEEDOMETER	
		23 1/2	

linkage Broke For Blade
angle Replaced with new linkage

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.



3130 St. Rte. 18

Norwalk, Ohio, 44857

419-663-2457


D-17

REPAIR ORDER

TIME PROMISED	A.M. ☐	P.M. ☐
YR.	MAKE	DATE
	Deere	8-9-18
MODEL	700K	WRITTEN BY
		Clint
LICENSE		MOTOR NO.
P.O. NO.		SPEEDOMETER
		2298

Hyd. leak Found Fitting rotted off nut
~~also~~ at Front of dozer For blade tilt
angle, also seen 4 the 3 other lines rotted they
Broke trying to loosening replaced with 4 new lines.

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.



3130 St. Rte. 18

Norwalk, Ohio, 44857

419-669-2457

REPAIR ORDER

TIME PROMISED	AM ☐	PM ☐
TRUCK	MAKE	DATE
	Paccar	5-15-18
MODEL	H50-82	DRIVER
		Jake
LICENSE		VEHICLE NO.
PO. NO.	D-17	SPEEDOMETER
		2101


QTY	PART NO.	DESCRIPTION	EACH AMOUNT
2	102276	Seal	
1	103223	O ring	
1	103350	gasket	
1	102287	Cable hddown	
1	104136	~	~
5	101440	~	~
1	103153	Gasket	
1	105401	DRUM	
1	103221	bearing sleeve	
2	A1P3934	CUPS	
2	A1P3935	CONES	
2	103341	WASHER	

- Replaced Drum on winch
- Put new seals and bearings
on Drum shaft
- Replaced cable

Serviced

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Signed



3130 St. Rte. 18

Norwalk, Ohio, 44857

419-660-2457

REPAIR ORDER

QTY	PART NO.	DESCRIPTION
1	T277554	hyd Tank gasket
4	R99702	O-Rings
1	6761	air filter
1	6766	
1	77505	
1	77505	oil filter
1	600104	fuel filter
1	600158	" "

Pulled cab
- Removed pump stack
- had No. 1 pump resealed
- Removed ~~and~~ ~~winch~~ winch disassembled
and ordered parts
- serviced and checked over

TO: John Deere	DATE: Feb 5
700 K	Jake
UNIT # D-17	HRS/MILES 2101