


M1



3130 St. Rte. 18

Norwalk, Ohio, 44657

419-668-2457

Set # 1X3215

REPAIR ORDER

QTY	PART NO.	DESCRIPTION	SALE AMOUNT
1	170081	Bolt	
1	170084	Bolt	
1	1551	Hyd Filter	
2	6207C3	bearing	
1	181-684	Dir. Shield	
1	115-779	Friction Washer 2.890"	
1	155-858	Internal Seal 1.875"	
1	501-398	Snap Ring	
1	137-210	35K Digging Chain 2P 62P	
1	135-1231	Duralook Right head	
1	135-637	Shock Teeth Right head	

Serviced greased chockloils, ~~and~~
 replaced both belts, replaced bearings seals in
 chain drive gearbox, New chain & Two Teeth

TIME TH	PROCESSED DATE	AM	PM
	8-4-20		
MODEL 1230H	WASHER		
LICENSE	NO. 111		
PLATE NO.			
SPEEDOMETER	No. 111		

Part #

Duralook 135-1230 Left
 Bolton 135-1231 Right

Bolton Shock

135-638 Left

135-639 Center

135-637 Right

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Signed