


Norwalk, Ohio, 44857



THE NEW YORK PUBLIC LIBRARY

300 HR Service


Caulier has Hrd back from
Cyl

A/C was charged but is thruing SE8701-11
Code so it does not work

QTY	PART NO.	DESCRIPTION	PAID AMOUNT
1	1880	oil	
1	3690	Fuel	
1	3683	Fuel	
1	2330	Air	
1	2816	Air	
1	1664	Hyd	
2	9979	Cab air	

I hereby authorize the above report to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my plant. An express receipt is to be acknowledged on above vehicle to contain the amount of repairs thereto. You will not be held responsible for loss or damages to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

ଆସାନ



3130 St. Rte. 18

Norwalk, Ohio, 44657

419-669-2457

REPAIR ORDER

300HR Service

QTY	PART NO.	DESCRIPTION	EST. AMOUNT
2	9979	Air	
1	2816	Air	
1	2330	Air	
1	1820	Oil	
1	3683	Fuel	
1	3090	Fuel	
1	1664	Hyd	

TIME PROMISED	DATE	AM	PM	☐
TH				
MODEL				
LICENSE	X16			
PLATE NO.				
SPEEDOMETER	1235 HR			

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Signed

Northwalk, Ohio, 44857

419693-2457

THE UNIVERSITY OF CHICAGO

300 hr Service

[illegible][illegible]

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicles for purposes of testing, inspection or delivery at my risk. An express agreement shall be acknowledged on above vehicle to covering the amount of repairs thereto. You will not be held responsible for loss or damages to vehicle or articles left in vehicle in case of fire, theft, accident or any other caused beyond your control.

উত্তর

COULD YOU BE A COACH?

Newark, Ohio, 44837

419-603-2457

中國人民日報

CITY	PART NO.	DESCRIPTION	PAID AMOUNT
1	1820	oil	
1	3690	Fuel	
1	3683	Fuel	
1	2330	air	
1	2816	air	
2	9979	air	

TIME FORWARDED	DATE	NAME	ROOM NO.
		NIGHTL 235	WATERMAN 8/6
		RECEIVED	EXPENSES

300Hr Service

A/C EVAP is plugged

I hereby authorize the above repair work to be done along with necessary materials. You find your employees may operate above vehicle for purpose of testing, inspection or delivery at my dock. An employee Mechanic's Lien is acknowledged on above vehicle to securing the amount of repair thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

பெரிய

W. H. Auden

419-663-2457

THE UNIVERSITY OF CHICAGO

TIME	PREMISED	A.M.	☐	P.M.	☐
YR.	MAKE	MODEL	WRITTEN BY		DATE
			MOTOR NO.		6-7-19
LICENSE	PRO. NO.	SPEEDOMETER		NS	
	X-16	5564			

Serviced

QTY	PART NO.	DESCRIPTION	SALE AMOUNT
1	1520	oil filter	
1	3690	fuel	
1	3683		
1	9979	oil	
1	1664	oil	
1	2330	oil	
1	2816		

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An approved Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

பொது

828

卷之四

419-663-2457		TIME RECEIVED		AM.	PM.
REPAIR ORDER		YR.	MI.	DATE	
replaced Hyd Hose and		MODEL	6600	4/3/14	
toped tank off with oil		LICENSE	233	JOHN P	
		POL. NO.	x16	ADJON NO.	
				STANDARDIZED	3036

11/11/2011 11:11 AM



Driver's Vehicle Inspection Report

Check ANY Defective Item and Give Details under "Remarks."

DATE: 1-29-19

TRUCK/TRACTOR NO. EX 16 - 235

- | | | |
|--|--|--|
| ☐ Air Compressor | ☐ Horn | ☐ Springs |
| ☐ Air Lines | ☐ Lights | ☐ Starter |
| ☐ Battery | Head - Stop | ☐ Steering |
| ☐ Brake Accessories | Tail - Dash | ☐ Tachograph |
| ☐ Brakes | Turn Indicators | ☐ Tires |
| ☐ Carburetor | ☐ Mirrors | ☐ Transmission |
| ☐ Clutch | ☐ Muffler | ☐ Wheels |
| ☐ Defroster | ☐ Oil Pressure | ☐ Windows |
| ☐ Drive Line | ☐ On-Board Recorder | ☐ Windshield Wipers |
| ☐ Engine | ☐ Radiator | ☐ Other |
| ☐ Fifth Wheel | ☐ Rear End | |
| ☐ Front Axle | ☐ Reflectors | |
| ☐ Fuel Tanks | ☐ Safety Equipment | |
| ☒ Heater | Fire Extinguisher | |
| | Flags - Flares - Fuses | |
| | Spare Bulbs & Fuses | |
| | Spare Seal Beam | |

FAW DOES NOT
WORK

TRAILER(S) NO(S). _____

- | | | |
|--|---------------------------------------|------------------------------------|
| ☐ Brake Connections | ☐ Hitch | ☐ Tarpaulin |
| ☐ Brakes | ☐ Landing Gear | ☐ Tires |
| ☐ Coupling Chains | ☐ Lights - All | ☐ Wheels |
| ☐ Coupling (King) Pin | ☐ Roof | ☐ Other |
| ☐ Doors | ☐ Springs | |

Remarks: _____

☐ Condition of the above vehicle is satisfactory

Drivers Signature _____

☒ Above Defects Corrected

☐ Above Defects need NOT Be Corrected For Safe Operation of Vehicle

Mechanic's Signature _____

Date _____

Driver's Signature _____

Date 1-29-19

Notwalk, Ohio 44857

國立中央圖書館


Installed new seat air cond

TIME PROCESSED	AM	☐	PM	☐
TR.	PERCE		DATE	2-20-17
MODEL	Volvo		WINTER	Josh T
LICENSE	235		REGION NO.	
	X19			
PLATE NO.			SPRINTING TIME	4716

I have my employees do the above repair work to be done along with necessary materials. You and your employees may operate above vehicles for purpose of loading, inspection or delivery at any time. An express Merchant's Lien is acknowledged on above vehicle to ensure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

3130 St. Rte. 18

Norwalk, Ohio, 44857



419-663-2457

REPAIR ORDER

TIME RECEIVED	DATE	AM	PM
TR.	Value		
MAKE	235		
MODEL	X16		
YEAR	2-20-19		
DRIVER	John T		
ADDRESS			
PHONE NO.			
STATION NO.			
STATION NAME			
STATION NO.			

replaced Blower motor and wiper motor
Installed used air pump for seat

reworked stop and go's handle on right side

seat Heater does not work do to short in Heat grid
Seat base slide needs new cable

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to receive the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or accident in vehicle in case of fire, theft, accident or any other cause beyond your control.

John T

Normal, Office 44857

49-693-2457

五

[illegible]

NAME	AM.	PLA.
<u>WILSON</u>	☐	☐
V.C.	DATE	TIME
	J.D.	2-20-19
WEIGHT		PARTICULARS
750 K.		65K 7
LITREAGE		MIDNIGHT
D.I.S.		
PO. NO.		SPEEDOMETER
		3338

replaced cab wire harness
replaced FNR and NS Switch
replaced Handels on rear side doors
replaced wiper black on ~~driving~~^{left} door

I hereby authorize and allow repair work to be done during this necessary mechanical. You and your employees may operate above's vehicle for purpose of testing, inspection or delivery at any time. An express Merchant's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or anything held in vehicle in case of fire, theft, accident or any other cause beyond your control.

CONSTRUCTION


419-6632457

TIME PROMISED	AM.	☐	PM.	☐
YR.	13	10/18	DATE	11-21-18
MODEL	ECR 2350L			
LEASE	NO. NO. NO.			
P.O. NO.	X116			
SPEEDOMETER	541170			
New net 0000310				

QTY	PART NO.	DESCRIPTION	SALE AMOUNT
392	17679	M20X1.5PX 1/2 (M30)	
		Brahma Balls	
392	012517-01	M20X1.5P Nuts	
2	KM 782-9	Rolls	
4	202V	Top Rollers	
110	110E 1471723	Bottom Rollers	
1	30003922-11	Valve Heater water flow valve	
		Wiper motor	

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damages to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Disputed



3130 St. Rte. 18
Norwalk, Ohio, 44857

419-663-2457


REPAIR ORDER

QTY	PART NO.	DESCRIPTION	SALE AMOUNT
1	1820	oil Filter	
1	3690	Fuel Filter	
1	3683	Fuel Filter	
1	1664	hyd. Filter	
1	2330	air Filter	
1	2816	air Filter	
2	9979	cab Filter	
2	4-D Battery		
1	1468 3230	Fuse panel Board	
1	VOE14612098	Fuel valve	
1	14539987	Fuel sight tube	

Full Service / Batterys were bad replaced with new / Fuse panel Board was bad Replaced with new one / Foot travel valve was bad replaced with new / Put new Fuel sight tube on

TIME PROMISED	DATE	AM.	PM.
YR.	MO.	DAY	
MODEL	235	9-13-78	
LICENSE		REGISTERED BY	
PIR. NO.		MOTOR NO.	
		SPEEDOMETER	4545 HR

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.



3130 St. Rte. 18

Norwalk, Ohio, 44132

419-669-2457

X-16

QTY	PART NO.	DESCRIPTION	REMARKS
1	393690	Fuel	
1	3683	Fuel	
1	1820	oil	
1	2816	inner air	
1	2330	outer air	
2	9979	Cabin	

Served

DATE	TIME	AM	PM
16/10	6-26-78		
NO. 235	235		
NAME	DATE		
16/10	6-26-78		
16/10	6-26-78		
16/10	6-26-78		

I hereby authorize the above to be done done with necessary repairs. You and your employees may operate at my risk. An Express Medical Lien is authorized on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or accident in vehicle in case of fire, theft, accident or any other cause beyond your control.


Signed

CITY	PART NO.	DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL PRICE	TAX	GRAND TOTAL
1	Windshield	VOE14570748					
1. Windshield 2. Windshield 3. Windshield 4. Windshield 5. Windshield 6. Windshield 7. Windshield 8. Windshield 9. Windshield 10. Windshield 11. Windshield 12. Windshield 13. Windshield 14. Windshield 15. Windshield 16. Windshield 17. Windshield 18. Windshield 19. Windshield 20. Windshield 21. Windshield 22. Windshield 23. Windshield 24. Windshield 25. Windshield 26. Windshield 27. Windshield 28. Windshield 29. Windshield 30. Windshield 31. Windshield 32. Windshield 33. Windshield 34. Windshield 35. Windshield 36. Windshield 37. Windshield 38. Windshield 39. Windshield 40. Windshield 41. Windshield 42. Windshield 43. Windshield 44. Windshield 45. Windshield 46. Windshield 47. Windshield 48. Windshield 49. Windshield 50. Windshield 51. Windshield 52. Windshield 53. Windshield 54. Windshield 55. Windshield 56. Windshield 57. Windshield 58. Windshield 59. Windshield 60. Windshield 61. Windshield 62. Windshield 63. Windshield 64. Windshield 65. Windshield 66. Windshield 67. Windshield 68. Windshield 69. Windshield 70. Windshield 71. Windshield 72. Windshield 73. Windshield 74. Windshield 75. Windshield 76. Windshield 77. Windshield 78. Windshield 79. Windshield 80. Windshield 81. Windshield 82. Windshield 83. Windshield 84. Windshield 85. Windshield 86. Windshield 87. Windshield 88. Windshield 89. Windshield 90. Windshield 91. Windshield 92. Windshield 93. Windshield 94. Windshield 95. Windshield 96. Windshield 97. Windshield 98. Windshield 99. Windshield 100. Windshield							

3130 St. Rte. 18

Norwalk, Ohio, 44857

419-663-2457



REPAIR ORDER


QTY	PART NO.	DESCRIPTION
2	14530363	Link (piece)
2		Track pin
2		Bushing (Track)

Took old link out of track chain. Replaced

w/new link + fixed 2 track pins.

Replaced

MAKE	DATE
Volvo	6-15-18
MODEL	WITTENBY
UNIT #	4258 hfs
	4258 hfs



3130 St. Rte. 18

Norwalk, Ohio, 44857

419-663-2457

REPAIR ORDER

QTY	PART NO.	DESCRIPTION	SALE AMOUNT
1	3/4 hose 5ft		
1	3/8 hose 3ft		
1	1/4 hose 5ft		

TIME PERMITTED YR.	MAKE V6/V8	DATE 9-28-77	P.M. ☐
MODEL 235	WRITTEN BY C/67		
LICENSE	MOTOR NO.		
P.O. NO.	SPEEDOMETER 3764 HA		

CITY PHONE

INSTRUCTIONS

hose was leaking going to swing motor replaced with new hose / also found 3/8 x 1/4 hose leaking by valve Body replaced with new hose

LABOR

TOTAL

OTHER

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

TOTAL

Signed

TOTAL

TOTAL

FORWARD

LABOR

PARTS

Gas, Oil, Grease


ACCESSORIES

Tires & Tubes

BODY SHOP

Outside Repairs

419-663-2457



五、四、三、二、一、

[illegible]

TIME	PLACED	A.M.	☐	P.M.	☐
YR.		MAKE			
MODEL	WRITTEN BY				
LICENSE	MOTOR NO.				
PO. NO.	SPEEDOMETER				

NAME Serviced by Dave Miller's
ADDRESS Crew on the job site.
CITY PHONE

INSTRUCTIONS

LABOR

Service

H/S 39 23

Due 4223

TOTAL

OTHER

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purpose of testing, inspection or delivery at my risk. An express Mechanic's Lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

QTS. OIL
Lbs. Grease
Lbs. Gear Lube
Trans. Fluid
Break Fluid

TOTAL

पञ्चमः

١٢٢

1



Driver's Vehicle Inspection Report

Check ANY Defective Item and Give Details under "Remarks."

DATE: 2-20-2017

TRUCK/TRACTOR NO. X-16 Volvo 235

- | | | |
|--|--|--|
| ☐ Air Compressor | ☐ Horn | ☐ Springs |
| ☐ Air Lines | ☐ Lights | ☐ Starter |
| ☐ Battery | Head – Stop | ☐ Steering |
| ☐ Brake Accessories | Tail – Dash | ☐ Tachograph |
| ☐ Brakes | Turn Indicators | ☐ Tires |
| ☐ Carburetor | ☐ Mirrors | ☐ Transmission |
| ☐ Clutch | ☐ Muffler | ☐ Wheels |
| ☐ Defroster | ☐ Oil Pressure | ☐ Windows |
| ☐ Drive Line | ☐ On-Board Recorder | ☐ Windshield Wipers |
| ☐ Engine | ☐ Radiator | ☒ Other |
| ☐ Fifth Wheel | ☐ Rear End | |
| ☐ Front Axle | ☐ Reflectors | |
| ☐ Fuel Tanks | ☐ Safety Equipment | |
| ☐ Heater | Fire Extinguisher | |
| | Flags – Flares – Fuses | |
| | Spare Bulbs & Fuses | |
| | Spare Seal Beam | |

TRAILER(S) NO(S). _____

- | | | |
|--|---------------------------------------|------------------------------------|
| ☐ Brake Connections | ☐ Hitch | ☐ Tarpaulin |
| ☐ Brakes | ☐ Landing Gear | ☐ Tires |
| ☐ Coupling Chains | ☐ Lights – All | ☐ Wheels |
| ☐ Coupling (King) Pin | ☐ Roof | ☐ Other |
| ☐ Doors | ☐ Springs | |

Remarks: Throttle knob missing

- ☐ Condition of the above vehicle is satisfactory

Drivers Signature _____

- ☐ Above Defects Corrected

- ☐ Above Defects need NOT Be Corrected For Safe Operation of Vehicle

Mechanic's Signature _____

Date _____

Driver's Signature _____

Date 2-20-2017



Driver's Vehicle Inspection Report

Check ANY Defective Item and Give Details under "Remarks."

DATE: 2-20-2017

TRUCK/TRACTOR NO. X-16 Volvo 235

- | | | |
|--|--|--|
| ☐ Air Compressor | ☐ Horn | ☐ Springs |
| ☐ Air Lines | ☐ Lights | ☐ Starter |
| ☐ Battery | Head – Stop | ☐ Steering |
| ☐ Brake Accessories | Tail – Dash | ☐ Tachograph |
| ☐ Brakes | Turn Indicators | ☐ Tires |
| ☐ Carburetor | ☐ Mirrors | ☐ Transmission |
| ☐ Clutch | ☐ Muffler | ☐ Wheels |
| ☐ Defroster | ☐ Oil Pressure | ☐ Windows |
| ☐ Drive Line | ☐ On-Board Recorder | ☐ Windshield Wipers |
| ☐ Engine | ☐ Radiator | ☒ Other |
| ☐ Fifth Wheel | ☐ Rear End | |
| ☐ Front Axle | ☐ Reflectors | |
| ☐ Fuel Tanks | ☐ Safety Equipment | |
| ☐ Heater | Fire Extinguisher | |
| | Flags – Flares – Fuses | |
| | Spare Bulbs & Fuses | |
| | Spare Seal Beam | |

TRAILER(S) NO(S). _____

- | | | |
|--|---------------------------------------|------------------------------------|
| ☐ Brake Connections | ☐ Hitch | ☐ Tarpaulin |
| ☐ Brakes | ☐ Landing Gear | ☐ Tires |
| ☐ Coupling Chains | ☐ Lights – All | ☐ Wheels |
| ☐ Coupling (King) Pin | ☐ Roof | ☐ Other |
| ☐ Doors | ☐ Springs | |

Remarks: Throttle Knob missing

Howard Farms

- ☐ Condition of the above vehicle is satisfactory

Drivers Signature _____

- ☐ Above Defects Corrected

- ☐ Above Defects need NOT Be Corrected For Safe Operation of Vehicle

Mechanic's Signature _____ Date _____

Driver's Signature [Signature] Date 2-20-2017



Driver's Vehicle Inspection Report

Check ANY Defective Item and Give Details under "Remarks."

DATE: 1-4-17

TRUCK/TRACTOR NO. X 16

- | | | |
|--|--|--|
| ☐ Air Compressor | ☐ Horn | ☐ Springs |
| ☐ Air Lines | ☐ Lights | ☐ Starter |
| ☐ Battery | Head – Stop | ☐ Steering |
| ☐ Brake Accessories | Tail – Dash | ☐ Tachograph |
| ☐ Brakes | Turn Indicators | ☐ Tires |
| ☐ Carburetor | ☐ Mirrors | ☐ Transmission |
| ☐ Clutch | ☐ Muffler | ☐ Wheels |
| ☐ Defroster | ☐ Oil Pressure | ☐ Windows |
| ☐ Drive Line | ☐ On-Board Recorder | ☐ Windshield Wipers |
| ☐ Engine | ☐ Radiator | ☐ Other |
| ☐ Fifth Wheel | ☐ Rear End | |
| ☐ Front Axle | ☐ Reflectors | |
| ☐ Fuel Tanks | ☐ Safety Equipment | |
| ☐ Heater | Fire Extinguisher | |
| | Flags – Flares – Fuses | |
| | Spare Bulbs & Fuses | |
| | Spare Seal Beam | |

TRAILER(S) NO(S). _____

- | | | |
|--|---------------------------------------|------------------------------------|
| ☐ Brake Connections | ☐ Hitch | ☐ Tarpaulin |
| ☐ Brakes | ☐ Landing Gear | ☐ Tires |
| ☐ Coupling Chains | ☐ Lights – All | ☐ Wheels |
| ☐ Coupling (King) Pin | ☐ Roof | ☐ Other |
| ☐ Doors | ☐ Springs | |

Remarks: Trottle Knob

☐ Condition of the above vehicle is satisfactory

Drivers Signature _____

☐ Above Defects Corrected

☐ Above Defects need NOT Be Corrected For Safe Operation of Vehicle

Mechanic's Signature _____ Date _____

Driver's Signature David Miller Date 1-4-17

9/1-X

Repair Order

[illegible][illegible]



Driver's Vehicle Inspection Report

Check ANY Defective Item and Give Details under "Remarks."

DATE: 3/16/17

TRUCK/TRACTOR NO. X-16

- | | | |
|--|--|--|
| ☐ Air Compressor | ☐ Horn | ☐ Springs |
| ☐ Air Lines | ☐ Lights | ☐ Starter |
| ☐ Battery | Head – Stop | ☐ Steering |
| ☐ Brake Accessories | Tail – Dash | ☐ Tachograph |
| ☐ Brakes | Turn Indicators | ☐ Tires |
| ☐ Carburetor | ☐ Mirrors | ☐ Transmission |
| ☐ Clutch | ☐ Muffler | ☐ Wheels |
| ☐ Defroster | ☐ Oil Pressure | ☐ Windows |
| ☐ Drive Line | ☐ On-Board Recorder | ☐ Windshield Wipers |
| ☐ Engine | ☐ Radiator | ☒ Other |
| ☐ Fifth Wheel | ☐ Rear End | |
| ☐ Front Axle | ☐ Reflectors | |
| ☐ Fuel Tanks | ☐ Safety Equipment | |
| ☐ Heater | Fire Extinguisher | |
| | Flags – Flares – Fuses | |
| | Spare Bulbs & Fuses | |
| | Spare Seal Beam | |

Red safety Arm on Left

TRAILER(S) NO(S). _____

- | | | |
|--|---------------------------------------|------------------------------------|
| ☐ Brake Connections | ☐ Hitch | ☐ Tarpaulin |
| ☐ Brakes | ☐ Landing Gear | ☐ Tires |
| ☐ Coupling Chains | ☐ Lights – All | ☐ Wheels |
| ☐ Coupling (King) Pin | ☐ Roof | ☐ Other |
| ☐ Doors | ☐ Springs | |

Remarks: Red safety Arm on Left and side of cab

☐ Condition of the above vehicle is satisfactory


Drivers Signature _____

☐ Above Defects Corrected

☐ Above Defects need NOT Be Corrected For Safe Operation of Vehicle

Mechanic's Signature Clint Nickoli Date _____

Driver's Signature Tony Gregory Date 3/16/17

**EQUIPMENT COMPANY**2512 J. ON PIKE
COLUMBUS, OH - 43223
(614) 636-4050P.O. BOX 32427
LOUISVILLE, KY 40232-2427
FAX (502) 459-8695**INVOICE**

Page: 1(1)

TIN 61-0445955

Invoice no	Date	Salesperson	Due date
119105002287	07/15/15		08/14/15

Sold to

Mark Haynes Construction Inc
3130 State Route 18
Norwalk, OH - 44857

Ship to

Mark Haynes Construction Inc
3130 State Route 18
Norwalk, OH - 44857

X/16

Customer	Order no	Customer PO no	Order dt	Delivery method	Dely no
2015279	3000222534	837379		Road transport	900

Machine Model	Machine SN	Payment terms	Delivery terms
		30 days from invoice date	Cost Insurance and Freight (... named port of destination)

Item no	Description	Inv	U/M	Sales price	Amount
14543246	PIPE	1	EA	100.18	100.18
21668613	SHOULDER SCREW	1	EA	0.99	0.99
22397427	KIT	1	EA	6,425.15	6,425.15
FRGHT	Freight Charge				243.13
RUSH	Rush charge				219.43
SHIP DIRECT NDA					

Matt - Received?
JUL 27 2015
yesReturned
8/3

65612369498723199501S199PF

Ordered from: A19
Send payment to: RUDD EQUIPMENT COMPANY
Dept 77432, P.O. BOX 77000
Detroit, MI 48277INTEREST AT THE RATE OF 1.5% PER MONTH WILL BE CHARGED ON THE UNPAID BALANCE.
INTEREST IS CALCULATED ON THE BASIS OF 18% PER ANNUM SIMPLE INTEREST.

Parts Total	6,526.32
Additional Charges	462.56
Sales Tax	507.12
Ohio Sales Tax	388.79
County Tax	84.52
City Tax	0.00
District Tax	33.81
AMOUNT TO PAY	7,496.00

PARTS RETURNED AFTER ONE YEAR OF DATE OF INVOICE ARE NOT ELIGIBLE FOR CREDIT



AUTO PARTS

100001753

LIBERTY AUTO PARTS
NAPA AUTO PARTS
230 REPUBLIC ST.
NORWALK, OH 44857
(419) 668-3370

Time: 12:22 Date: 07/10/2015 Page: 1/1

Employee: 4468 , Ronald
Sales Rep: 178 , Alicia
Accounting Day: 8

2457

Mark Haynes Construction
3130 ST RT 18
Norwalk, OH 44857

Anticipated Time:

Attention:

Tax Exemption:

PO#:

Terms: N30

SOLD TO

Part Number	Line	Description	Quantity	Price	Net	Total
7001006	BK	TEST KIT	1.00	50.70	38.6300	38.63 T
7001366	BK	BLOCK TESTER FLUID	1.00	7.39	5.6300	5.63 T

X-16

Customer Signature

ALL GOODS RETURNED MUST BE ACCOMPANIED BY THIS INVOICE

REF BY _____ VER BY _____

CUSTOMER COPY

1000017539545287

OCR

954528



Invoice Number

Subtotal 44.26
TAXTABLE 3 7.2500% 3.21

Total 47.47

Charge Sale 47.47